PRC Environmental Management, Inc. 233 North Michigan Avenue Suite 1621 Chicago, IL 60601 312-856-8700 Fax 312-938-0118



PRELIMINARY ASSESSMENT/ VISUAL SITE INSPECTION

GENERAL ELECTRIC COMPANY ELECTRICAL DISTRIBUTION AND CONTROL DIVISION BLOOMINGTON, ILLINOIS ILD 005 453 691

FINAL REPORT

Prepared for

U.S. ENVIRONMENTAL PROTECTION AGENCY Office of Waste Programs Enforcement Washington, DC 20460

Work Assignment No. : C05087

EPA Region : 5

 Site No.
 :
 ILD 005 453 691

 Date Prepared
 :
 October 16, 1992

 Contract No.
 :
 68-W9-0006

 PRC No.
 :
 009-C05087-IL2V

Prepared by : Resource Applications, Inc.

(Laura Czajkowski)

Contractor Project Manager : Shin Ahn
Telephone No. : (312) 856-8700
EPA Work Assignment Manager : Kevin Pierard
Telephone No. : (312) 886-4448

EPA Region 5 Records Ctr.






TABLE OF CONTENTS

Section	<u>Page</u>		
EXECUTIVE SUMMARY ES-			
1.0	INTRODUCTION 1		
2.0	FACILITY DESCRIPTION		
	2.1FACILITY LOCATION42.2FACILITY OPERATIONS42.3WASTE GENERATING PROCESSES62.4HISTORY OF DOCUMENTED RELEASES132.5REGULATORY HISTORY142.6ENVIRONMENTAL SETTING15		
	2.6.1 Climate 16 2.6.2 Flood Plain and Surface Water 16 2.6.3 Geology and Soils 16 2.6.4 Ground Water 17		
	2.7 RECEPTORS		
3.0	SOLID WASTE MANAGEMENT UNITS		
4.0	AREAS OF CONCERN		
5.0	CONCLUSIONS AND RECOMMENDATIONS		
REFE	ENCES 38		
Attach	<u>nent</u>		
Α	EPA PRELIMINARY ASSESSMENT FORM 2070-12		
В	VISUAL SITE INSPECTION SUMMARY AND PHOTOGRAPHS		
С	VISUAL SITE INSPECTION FIELD NOTES		
D	SAMPLING RESULTS FOR SWMUs 5.6. AND 7		

LIST OF TABLES

	<u>Table</u>	<u>Pa</u>	ge
M fi	1	SOLID WASTE MANAGEMENT UNITS (SWMU)	7
	2	SOLID WASTES	9
	3	SWMU SUMMARY AND AOC SUMMARY	33
1 +			
•		LIST OF FIGURES	
	<u>Figure</u>	<u>Pa</u>	g <u>e</u>
M	1	FACILITY LOCATION	5
a j	2	FACILITY LAYOUT/SWMU AND AOC LOCATIONS	8
·	3	WASTEWATER TREATMENT UNIT PROCESS FLOW DIAGRAM	24
<u></u>			
-			
•			



EXECUTIVE SUMMARY



Resource Applications, Inc. (RAI) performed a preliminary assessment and visual site inspection (PA/VSI) to identify and assess the existence and likelihood of releases from solid waste management units (SWMU) and other areas of concern (AOC) at the General Electric Company-Electrical Distribution and Control Division (GE) facility in Bloomington, Illinois. This summary highlights the results of the PA/VSI and the potential for releases of hazardous wastes or hazardous constituents from SWMUs and AOCs identified. In addition, a completed U.S. Environmental Protection Agency (EPA) Preliminary Assessment Form (EPA Form 2070-12) is included in Attachment A to assist in prioritization of RCRA facilities for corrective action.

The GE facility manufactures electric motor control equipment such as starters, reversers, relays, push buttons, switches, and sensors. The facility generates and manages the following waste streams: waste paint (F003/F005), paint sludge (D001), spent wastewater treatment sludge (F006), spent 1,1,1-trichloroethane (TCA) (F001/F002), nonhazardous waste oil and coolant, nonhazardous polyester paint waste, and nonhazardous grinding sludge. The facility has operated at its current location since 1955. The facility occupies 65 acres in a commercial area and employs about 350 people. The facility's regulatory status is that of a large-quantity generator. Before GE occupied the site, the land was used for agricultural purposes. The facility is currently closing two storage areas that managed hazardous waste for greater than 90 days. The units are inactive and no longer store any type of waste. A revised closure plan was approved by the Illinois Environmental Protection Agency (IEPA) in a letter dated June 12, 1991. Two other storage units are active and manage hazardous waste for less than 90 days.

The PA/VSI identified the following eight SWMUs and one AOC at the facility:

Solid Waste Management Units

- 1. Hazardous Waste Storage Area No. 1
- 2. Nonhazardous Waste Storage Areas
- 3. Wastewater Treatment Unit
- 4. Hazardous Waste Satellite Accumulation Areas
- 5. Former Hazardous Waste Storage Area No. 1
- 6. Former Hazardous Waste Storage Area No. 2
- 7. Former Incinerator

8. Hazardous Waste Storage Area No. 2

ENFORCEMENT CONFIDENTIAL

Area of Concern

1. Trichloroethene Spill Area

The GE facility occupies 65 acres in a commercial area in Bloomington, Illinois. Bloomington has a population of about 45,000.

The GE facility is bordered on the north by commercial property and GE park, on the west by commercial property, on the south by commercial property, and on the east by vacant land. The nearest school, Stevenson School, is located about 0.5 mile south of the facility. Facility access is controlled by a north gate with a security guard present 24 hours a day, 7 days a week. There is also a south gate that is kept locked. The entire site is secured by a 7-foot chain-link fence with barbed wire on top.

The nearest surface water body, Sugar Creek, is located 0.2 mile north of the facility and is used for recreational purposes. Other surface water bodies in the area include Lake Bloomington which is located 6 miles north of the GE facility.

Surface water from Lake Bloomington is used as the drinking water supply. There are no drinking water wells or industrial wells located within 3 miles of the facility.

Sensitive environments are not located on site. There are no wetland areas or sensitive environments located within 3 miles of the facility.

The potential for release to ground water and surface water is low. Hazardous waste is stored indoors in closed 55-gallon containers on 8-inch thick concrete, except for SWMU 8. The hazardous waste at SWMU 8 is stored outdoors in a closed roll-off box on 8-inch thick concrete. The water table in the vicinity of the facility is at a depth of approximately 180 feet below ground surface. Soil borings performed on the east side of the facility encountered clay soils containing minimum ground water to the drilled depth of 31 feet. The facility is outside the 500-year flood plain, with the closest surface water body, Sugar Creek, located 0.2 miles north of the facility.

The potential for release to air is low. Hazardous wastes are stored in closed 55-gallon containers and 20-cubic-yard roll-off boxes.

There was a release of trichloroethene (TCE) to on-site soils on January 24, 1991. An aboveground TCE product storage tank located outdoors on the east side of the facility was damaged. One hundred gallons of TCE spilled onto concrete and soil (AOC 1). Approximately 50 cubic yards of soil have been removed. Soil sampling in October 1991 revealed that TCE contamination was still present. The soil sampling also revealed lead and cadmium were present in the area of the Former Incinerator (SWMU 7). Cadmium contamination was detected by the Former Hazardous Waste Storage Area No. 1 (SWMU 5). TCE contamination was detected in the area of the Former Hazardous Waste Storage Area No. 2 (SWMU 6).

RAI recommends that the facility continue remediation of the TCE contaminated soil of AOC 1 and SWMU 6. RAI also recommends remediating the soil in the areas of cadmium and lead contamination at SWMUs 5 and 7. RAI recommends no further action for SWMUs 1, 2, 3, 4, and 8.

1.0 INTRODUCTION

PRC Environmental Management, Inc. (PRC) received Work Assignment No. C05087 from the U.S. Environmental Protection Agency (EPA) under Contract No. 68-W9-0006 (TES 9) to conduct preliminary assessments (PA) and visual site inspections (VSI) of hazardous waste treatment and storage facilities in Region 5. Resource Applications, Inc. (RAI), TES 9 team member, provided the necessary assistance to complete the PA/VSI activities for the General Electric Company-Electrical Distribution and Control Division (GE).

As part of the EPA Region 5 Environmental Priorities Initiative, the RCRA and CERCLA programs are working together to identify and address RCRA facilities that have a high priority for corrective action using applicable RCRA and CERCLA authorities. The PA/VSI is the first step in the process of prioritizing facilities for corrective action. Through the PA/VSI process, enough information is obtained to characterize a facility's actual or potential releases to the environment from solid waste management units (SWMU) and areas of concern (AOC).

A SWMU is defined as any discernible unit at a RCRA facility in which solid wastes have been placed and from which hazardous constituents might migrate, regardless of whether the unit was intended to manage solid or hazardous waste.

The SWMU definition includes the following:

- RCRA-regulated units, such as container storage areas, tanks, surface impoundments, waste piles, land treatment units, landfills, incinerators, and underground injection wells
- Closed and abandoned units
- Recycling units, wastewater treatment units, and other units that EPA has generally exempted from standards applicable to hazardous waste management units
- Areas contaminated by routine and systematic releases of wastes or hazardous constituents. Such areas might include a wood preservative drippage area, a loading-unloading area, or an area where solvent used to wash large parts has continually dripped onto soils.

An AOC is defined as any area where a release to the environment of hazardous waste or constituents has occurred or is suspected to have occurred on a nonroutine and nonsystematic basis. This includes any area where such a release in the future is judged to be a strong possibility.

The purpose of the PA is as follows:

- Identify SWMUs and AOCs at the facility.
- Obtain information on the operational history of the facility.
- Obtain information on releases from any units at the facility.
- Identify data gaps and other informational needs to be filled during the VSI.

The PA generally includes review of all relevant documents and files located at state offices and at the EPA Region 5 office in Chicago.

The purpose of the VSI is as follows:

- Identify SWMUs and AOCs not discovered during the PA.
- Identify releases not discovered during the PA.
- Provide a specific description of the environmental setting.
- Provide information on release pathways and the potential for releases to each medium.
- Confirm information obtained during the PA regarding operations, SWMUs, AOCs, and releases.

The VSI includes interviewing appropriate facility staff, inspecting the entire facility to identify all SWMUs and AOCs, photographing all SWMUs, identifying evidence of releases, initially identifying potential sampling locations, and obtaining all information necessary to complete the PA/VSI report.

This report documents the results of a PA/VSI of the GE facility in Bloomington, Illinois. The PA was completed on January 22, 1992. RAI gathered and reviewed information from the Illinois

Environmental Protection Agency (IEPA) and from EPA Region 5 RCRA files. RAI also reviewed relevant publications from the U.S. Department of Agriculture (USDA), U.S. Geological Survey (USGS), U.S. Department of Commerce (USDC), and the Federal Emergency Management Agency (FEMA). The VSI was conducted on January 24, 1992. It included interviews with facility representatives and a walk-through inspection of the facility. Eight SWMUs and one AOC were identified at the facility.

RAI completed EPA Form 2070-12 using information gathered during the PA/VSI. This form is included in Attachment A. The VSI is summarized and 12 inspection photographs are included in Attachment B. Field notes from the VSI are included in Attachment C. Attachment D is soil sampling results for SWMUs 5, 6, and 7.

2.0 FACILITY DESCRIPTION

This section describes the facility's location, past and present operations (including waste management practices), waste generating processes, history of documented releases, regulatory history, environmental setting, and receptors.

2.1 FACILITY LOCATION

The GE facility is located at 1601 G.E. Road in Bloomington, McLean County, Illinois (latitude 40°30'00" N and longitude 88°57'00" W), as shown in Figure 1. The facility occupies 65 acres in a commercial area.


The GE facility is bordered on the north by commercial property and GE park, on the west by commercial property, on the south by commercial property, and on the east by vacant land.

2.2 FACILITY OPERATIONS

The GE facility manufactures electric motor control equipment such as starters, reversers, relays, push buttons, switches, and sensors. The primary processes are the plating, molding, painting, and assembly of parts. The manufactured electric motor control equipment is also packed and stored at the facility.

GE receives most of its parts from other GE plants. This facility does some manufacturing of molded plastic parts and punched steel parts. The metal parts that need to be cleaned and plated are moved to the east end of the facility. Cleaning operations consist of vapor degreasers and in February 1992 GE plans to have an aqueous washer installed to replace the vapor degreasers. After machining parts are washed with phosphoric acid soap. Before heat treatment in the painting operation some parts are washed with a sodium carbonate solution.

Plating operations consist of gold, nickel, tin, and zinc plating for assorted metals. GE operates seven plating lines, that are located in two rooms on the east side of the facility near



receiving. The gold plating line is located in a small room. The other six lines are located in a larger plating room. After caustic and acid cleaning and plating, the parts are moved to assembly.

The parts that need to be painted are taken to the painting area. Small parts are powder painted with epoxy or polyester paint. After the parts are painted, they are dried in the baking oven. About 80 percent of the parts are painted by another process, electrophoretic coating. This process also requires subsequent oven drying after the parts are painted. The parts are moved through the painting process by conveyor hooks. When the painting process is finished, the parts are then assembled and packaged.

Wastewater generated from the plating and painting processes is treated in the Wastewater Treatment Unit (SWMU 3). Treatment of the wastewaters at the wastewater treatment unit includes cyanide destruction, chrome reduction, pH adjustment, clarifiers, filter presses, and other related equipment. Hazardous waste is stored in the Hazardous Waste Storage Area No. 1 (SWMU 1) on the east side of the building. In February 1992, GE plans to begin operation of an aqueous washer to replace the vapor degreasers. Facility SWMUs are identified in Table 1. The facility layout, including SWMUs and AOCs, is shown in Figure 2.

The facility has operated at its current location since 1955 and employs about 350 people. The facility consists of one main building, which is 360,000 square feet, and two parking lots that are located on the north side of the building. Since operations began, GE has owned and operated the facility. Before 1955, the site was used for agricultural purposes.

2.3 WASTE GENERATING PROCESSES

The primary waste streams generated at the GE facility are waste paint (F003/F005), paint sludge (D001), spent TCA (F001/F002), wastewater treatment sludge (F006), nonhazardous waste oil and coolant, and special waste polyester paint and grinding sludge. These wastes are generated during the production of electric control equipment. Wastes generated at the facility are discussed below and are summarized in Table 2. Monthly and annual generation rates presented are based on 1991 waste generation data.

TABLE 1
SOLID WASTE MANAGEMENT UNITS (SWMU)

SWMU Number	SWMU Name	RCRA Hazardous Wanagement Unit*	aste Status
1	Hazardous Waste Storage Area No. 1	No	Active, less than 90-day storage
2	Nonhazardous Waste Storage Areas	No	Active
3	Wastewater Treatment Unit	No	Active
4	Hazardous Waste Satellite Accumulation Areas	No	Active
5	Former Hazardous Waste Storage Area No. 1	Yes	Inactive, formerly used for greater than 90-day storage; currently undergoing RCRA closure
6	Former Hazardous Waste Storage Area No. 2	No	Inactive, formerly used for greater than 90-day storage; currently undergoing RCRA closure
7	Former Incinerator	No	Inactive
8	Hazardous Waste Storage Area No. 2	No	Active, less than 90-day storage

Note:

^{*} A RCRA hazardous waste management unit is one that currently requires or formerly required submittal of a RCRA Part A or Part B permit application.




TABLE 2
SOLID WASTES

Waste/EPA Waste Code	Source	Primary Management Unit*
Waste paint/F003/F005	Cleaning of paint booth's hand-held spray gun and dried paint	1 and 4
Paint sludge/D001	Cleaning of both the paint booth's water curtain and the electrophoretic dip tank	1
Spent TCA/F001/F002	Vapor degreaser and cleaning of baths in plating process	1, 5, and 6
Wastewater treatment sludge and spent filters/F006	Wastewater Treatment Unit	3, 5, 6, and 8
Special waste polyester paint/NA**	Powder paint booth	2
Special waste grinding sludge/NA**	Grinding machine	2
Nonhazardous waste oil and coolant/NA**	Maintenance of machines	2
Nonhazardous washer sludge/NA**	Cleaning of parts	2
Spent aerosol cans/NA**	Maintenance	1 and 4
Spent TCE/F001	Degreaser	5
Spent naphtha/D001	Degreaser	5 and 6

Note:

- * Primary management unit refers to a SWMU that currently manages or formerly managed the waste.
- ** Nonapplicable (NA) designates nonhazardous waste.
- *** Waiting for lab analysis for determination of hazardous constituents.

TABLE 2 (cont'd)

SOLID WASTES

Waste/EPA Waste Code		Source	Primary Management Unit*	
Spent Freon/F001		Degreaser	5 and 6	
Spent methylene chloride/F002		Painting process	5 and 6	
Spent ferric chloride/D002		Chemical etching of circuit boards	5 and 6	
Office waste/NA**		Administrative areas	7	
Concrete/NA***		Trichloroethene Spill Area	8	
Note:	Note:			
*	Primary management unit refers to a SWMU that currently manages or formerly managed the waste.			
**	Nonapplicable (NA) designates nonhazardous waste.			
***	* Waiting for lab analysis for determination of hazardous constituents.			

During the painting process, waste paint (F003/F005) is generated from cleaning spray guns in the paint booths. This waste consists of dried paint, gloves, and rags and is accumulated in 15-gallon metal containers at the Hazardous Waste Satellite Accumulation Areas (SWMU 4). The paint waste is transferred into 55-gallon drums and stored in Hazardous Waste Drum Storage Area No. 1 (SWMU 1). Another painting process waste, paint sludge (D001), is generated when the paint booth water curtain's settling tank is cleaned and also when the electrophoretic dip tank is cleaned. The paint sludge is put into 55-gallon drums and stored in SWMU 1. Liquid paint waste generated from the cleaning of the electrophoretic dip tank is discharged by hose to a drain in the paint room that leads to the Wastewater Treatment Unit (SWMU 3). About 81 gallons per month of paint waste (F003/F005) are generated. Approximately 103 gallons per month of paint sludge (D001) are generated. Both wastes are picked up by Safety-Kleen Corporation (Safety-Kleen) of Dolton, Illinois and incinerated.

Spent TCA (F001/F002) is generated from a vapor degreaser and also when the baths in the plating process are cleaned. Still bottoms from the degreaser and waste from the baths are put into 55-gallon drums and stored in SWMU 1. About 71 gallons of this waste are generated per month. Safety-Kleen transports this waste to their facility in Dolton, Illinois, for recycling.

Wastewater treatment sludge (F006) is generated from the Wastewater Treatment Unit (SWMU 3) during the treatment of plating and painting process wastewaters at the facility. This waste is transferred from 1-cubic-yard steel dumpsters to roll-off boxes and stored in Hazardous Waste Storage Area No. 2 (SWMU 8). About 234 gallons of this waste are generated monthly. Spent filters (F006) from the filter press are also put into the roll-off boxes and stored at SWMU 8. About 20 cubic yards of this waste are generated when the filters are replaced. The wastewater treatment sludge and filters are transported off site by Envirite, Inc., of Harvey, Illinois, to reclaim the metals using a pyrolitic recovery technique. The treated wastewater is discharged into the sanitary sewer. The Bloomington and Normal Water Reclamation District (BNWRD) requires GE to monitor the wastewater that is discharged into the sewer three times a week using 24-hour composites.

A nonhazardous polyester paint waste is generated during the powder painting of some of GE's products. This waste is stored in one 55-gallon drum in one of the Nonhazardous Waste Storage Areas (SWMU 2). The polyester paint waste is manifested as a special waste. About 12

cubic yards of this waste are generated monthly. The waste is transported by Commercial Disposal, Inc. (CDI) of Bloomington, Illinois, and landfilled at the Sexton-McLean County Landfill in Bloomington, Illinois.

The GE facility also generates a grinding sludge that is manifested as a special waste. This waste is generated from the grinding machine and cannot be recycled back into the process. A maximum of 50 cubic yards of this waste is generated annually. The grinding sludge is transported by CDI to be disposed of at the Sexton-McLean County Landfill in Bloomington, Illinois.

During maintenance of machines, nonhazardous waste oil and waste coolant are generated. This waste is accumulated in a container and then transferred to a 55-gallon drum, and stored in SWMU 2. About 160 gallons of this waste are generated monthly. This waste is picked up by Safety-Kleen for fuel blending.

After machining, parts are cleaned by a soap and water solution in the machining area of the facility. This process generates a nonhazardous washer sludge. The washer sludge is placed into 55-gallon steel drums and stored at SWMU 2. About 5 gallons of this waste is generated yearly. This waste is being stored at SWMU 2, and has not been disposed of since 1985.

Spent aerosol cans are generated from regular maintenance in the facility. GE is currently accumulating the cans at SWMU 4 and then storing them at SWMU 1. GE has not accumulated enough of this waste to dispose of it.

Assorted scrap metals are generated during the machining and punching processes. The scrap metal is segregated into barrels according to composition and then recycled back into the process. The scrap metal that cannot be recycled at the facility is sold to Morris Tick, Inc., a local recycler in Bloomington, Illinois.

GE previously generated spent TCE (F001), spent naphtha (D001), and spent Freon (F001) from the degreasing of metal parts. The facility decreased its use of those chemicals and now uses vapor degreasers serviced by Safety-Kleen. The hazardous wastes generated from degreasing were

put into 55-gallon drums and stored in the Former Hazardous Waste Storage Area No. 1 (SWMU 5). Spent Freon was also stored in the Former Hazardous Waste Storage Area No. 2 (SWMU 6).

Other wastes formerly generated were spent methylene chloride (F002) from the painting process, and spent ferric chloride (D002) generated from chemical etching of circuit boards. These wastes were put into 55-gallon drums and stored in both SWMUs 5 and 6.

Office trash and wood skids were incinerated by the Former Incinerator (SWMU 7). The incinerator was removed in 1972.

During soil excavation of the Trichloroethene Spill Area concrete was removed and placed in two steel dumpsters in SWMU 8. GE is waiting for lab analysis to dispose of this waste.

The GE facility has 15 vapor degreasers throughout the plant. They are all serviced and maintained by Safety-Kleen. By the end of February 1992, GE plans to have installed an aqueous washer to clean parts and would replace the vapor degreasers.

2.4 HISTORY OF DOCUMENTED RELEASES

This section discusses the history of documented releases to ground water, surface water, air, and on-site soils at the GE facility.

On January 24, 1991, approximately 100 gallons of TCE were spilled onto a cement pad and surrounding soil from a 1,000-gallon aboveground storage tank. The spill was reported to the Illinois Emergency Services and Disaster Agency (IESDA) on January 24, 1991 (IESDA, 1991). A broken valve on the tank caused this release. About 50 cubic yards of TCE-contaminated soil have been removed. The TCE tank and remaining TCE product have been removed off site. The TCE-contaminated soil was transported by Peoria Disposal Company and disposed of by Envirosafe Services of Ohio, Inc., of Oregon, Ohio (GE, 1991). Concrete that was removed in the area is awaiting laboratory analysis prior to disposal. The concrete is currently being managed in two dumpsters (SWMU 8). The TCE tank was cleaned and sold to Morris Tick, Inc., of Bloomington, Illinois. GE has contracted Harza Environmental Services, Inc. (Harza) to perform sampling of the

area (AOC 1) to determine if further remediation is necessary. GE also contracted Harza to perform soil sampling of the two former hazardous waste storage areas (SWMUs 5 and 6) and the area of the Former Incinerator (SWMU 7). Sampling was conducted in October 1991, according to the closure plan that was approved by IEPA on June 12, 1991 (IEPA, 1991a).

Twelve soil samples were collected from six locations in the area of SWMU 5. The toxicity characteristic leaching procedure (TCLP) results for cadmium revealed that some samples exceeded the RCRA regulatory level of 1 milligram per liter (mg/L).

Ten soil samples were collected from five locations in the area of SWMU 6. TCE was detected in samples taken around the southern half of the pad. Harza determined this was caused from the 1991 TCE spill.

For soil samples collected in the area of the Former Incinerator (SWMU 7), TCLP detected cadmium and lead. Included in Attachment D are the summary results from sampling in the location of SWMUs 5, 6, and 7. GE submitted the sampling results to IEPA in December 1991 and is awaiting IEPA's approval.

2.5 REGULATORY HISTORY

GE submitted a Notification of Hazardous Waste Activity to EPA on August 11, 1980 (GE, 1980a). The facility submitted a RCRA Part A permit application on November 11, 1980 (GE, 1980b). This application listed the following process codes and capacities: a drum storage unit (S01) with a 11,000-gallon capacity (SWMU 5), and a tank unit (T01) with a 6,000-gallon per hour capacity.

The application listed the following waste codes: F001, F007, F008, F009, F010, and F017. The tank unit (T01) with a 6,000-gallon per hour capacity is a RCRA exempt wastewater treatment unit that was listed on the Part A in error. GE amended their Part A permit application on January 26, 1985 and removed its wastewater treatment unit. This application listed the following wastes F001, F002, F003, F006, D001, and D007 (GE, 1985). GE again amended their Part A permit

application on May 23, 1986. This application listed the following waste codes: F001, F002, D001, F003, F005, D007 and F006 (GE, 1986).

GE generated a spent silver solution (F007, F008, F009) from a silver plating line before the Wastewater Treatment Unit was upgraded. Facility representatives also stated that the F010 waste listed on the Part A permit was probably never generated. GE also generated a F017 waste from an industrial printing process. In GE's amended Part A permit application this waste was reclassified as F003/F005. GE is currently in the process of amending their Part A permit (GE, 1992c).

The facility is currently closing the following units: the Former Hazardous Waste Storage Area No. 1 (SWMU 5) and the Former Hazardous Waste Storage Area No. 2 (SWMU 6). The Former Hazardous Waste Storage Area No. 2 was an unpermitted storage area that was used from 1980 to 1981. IEPA approved the May 1991 closure plan on June 12, 1991 (IEPA, 1991a). Facility representatives plan to complete closure some time in 1992 upon IEPA approval.

In the past, GE has had minor RCRA compliance problems. These violations, observed during routine inspections by IEPA from 1981 through 1991, pertained mainly to deficiencies in paperwork such as inspection logs, training records, contingency plans, waste analysis plan, closure plan, labelling drums, and land disposal restriction notifications. No compliance orders were issued as a result of the inspections (IEPA, 1981, 1983a, 1983b, 1984a, 1984b, 1986, 1987, 1989, 1991b).

The facility is required to have one all-encompassing air permit that regulates numerous production processes. The air permit, No. 74070052, expires on December 5, 1993 (IEPA, 1990). The facility is not required to have a National Pollutant Discharge Elimination System (NPDES) permit. BNWRD requires GE to have a permit to discharge wastewater into the sanitary sewer. The discharge permit, BNWRD 92-01, expires on December 31, 1992 (BNWRD, 1991).

2.6 ENVIRONMENTAL SETTING

This section describes the climate, flood plain and surface water, geology and soils, and ground water in the vicinity of the GE facility.

2.6.1 Climate

The climate in McLean County is typically continental with cold winters, warm summers, and frequent short period fluctuations in temperature, humidity, cloudiness, and wind direction. The average daily temperature is 52.5°F. The lowest average daily temperature is 17.0°F in January. The highest average daily temperature is 86.6°F in July.

The total annual precipitation for the county is 36.41 inches (NOAA, 1975). The mean annual lake evaporation for the area is about 32.5 inches (USDC, 1968). The 1-year, 24-hour maximum rainfall is 3.89 inches (NOAA, 1975).

The prevailing wind is from the south. Average wind speed is highest in March at 12.1 miles per hour from the west-northwest. The average annual wind speed is 10.0 miles per hour (NOAA, 1990).

2.6.2 Flood Plain and Surface Water

The facility is located outside the 100-year flood plain, in an area of minimal flooding (BNWRD, 1992). The nearest surface water, Sugar Creek, is located 0.2 mile north of the facility building, and is used for recreational purposes. This surface water body discharges via Kickapoo Creek, Salt Creek, and Greenview Creek into the Sangamon River. The Sangamon River ultimately discharges into the Illinois River.

Surface water drainage at the facility is directed into the sewer, which flows to BNWRD treatment works. The facility does not hold a NPDES permit. There are no other major surface water bodies or wetlands in the vicinity.

2.6.3 Geology and Soils

The facility is underlain by soils of the Urban land complex; this unit consists of areas covered by pavement and buildings, where the original soils are unidentifiable due to cutting and

filling, during construction. Surface runoff is rapid; water is diverted into storm drainage systems (USDA, 1992).

No site-specific information was available regarding drift or bedrock geology; thus regional information is presented below. Unconsolidated deposits, or drift, of Pleistocene and recent ages overlie the eroded bedrock surface. The bulk of drift deposits are known as till, which is a relatively impermeable, clayey silt deposit. The uppermost Wisconsinan deposits are generally fine-grained sandy silts, and are approximately 100 feet thick. Beneath these, the Illinoian deposits contain widespread lenses of sand and gravel intercalated in the till; these lenses are a fairly significant source of ground water. Pre-Illinoian deposits do not occur in the Bloomington-Normal area. The approximate total thickness of drift deposits beneath the facility is 200 feet (Stephenson, 1967).

The uppermost bedrock underlying the facility is of Pennsylvanian age, and consists of impermeable shale, with some thin, discontinuous lenses of limestone and sandstone. These rocks are part of the Carbondale and Modesto formations. Beneath the Pennsylvanian deposits are Mississippian rocks, mainly consisting of limestones with some shales, siltstones, and sandstones. Silurian rocks of the Alexandrian and Niagaran formations occur below the Mississippian rocks; these are predominantly dolomites. The Ordovician Maquoketa Shale is a 50-foot-thick layer of impermeable shale which acts as a cap on the underlying Galena-Platteville dolomites and limestones, which are about 350 feet thick. The Glenwood-St. Peter sandstones and sandy limestones lie beneath the carbonates, and are 250 feet thick. The Knox Megagroup consists of 1,250 feet of Ordovician and Cambrian dolomitic sandstones and dolomites, and is underlain by the Ironton-Galesville sandstone (200 feet thick), and the Basal Sandstone Confining Unit, a 400-foot series of dolomites and impermeable shales. The deepest Paleozoic rocks are the friable white sandstones of the Elmhurst-Mount Simon series, which are approximately 2,500 feet thick and are underlain by Precambrian basement at a depth of about 6,000 feet (Visocky, et al., 1985).

2.6.4 Ground Water

No site-specific information was available regarding ground water; thus regional information is presented below. Ground water is derived from lenses of sand and gravel within the drift deposits. In the upper (Wisconsinan) units, there are a few thin, wide sand and gravel lenses, while the lower

(Illinoian) deposits are about 20% sand and gravel with the bulk of the lenses being in the lower half of the drift (between 150 and 200 feet below ground surface). These lower deposits have the best potential as aquifers. The till matrix is sufficiently impermeable that it will act as an aquitard between productive sand and gravel aquifers. Recharge rates for the sand and gravel aquifers are estimated at 150,000 gallons per day (gpd) per square mile, and recharge generally occurs as vertical leakage from precipitation. Wells penetrating Wisconsinan deposits may yield from 3 gallons per minute (gpm) to 510 gpm; those completed in Illinoian deposits yield from 3 gpm to 885 gpm (Stephenson, 1967).

The Elmhurst-Mount Simon sandstones, the Knox Megagroup, the Glenwood-St. Peter sandstones, and the Galena-Platteville dolomites yield moderate quantities of ground water. The most productive bedrock aquifer is the Cambrian Ironton-Galesville sandstone, which may yield in excess of 500 gpm. This unit is about 200 feet thick in the vicinity of the site. The Niagaran and Alexandrian dolomitic rocks of Silurian age are inconsistent in their yield, but may produce more than 1,000 gpm in fractured zones. The Cambrian and Ordovician aquifers are confined by the relatively impermeable Maquoketa Shale, although some recharge occurs by leakage through this unit. The Silurian aquifer exists under leaky artesian conditions, and recharge is from percolation of precipitation through the drift deposits. Ground water flow is to the west and north, toward Spring Creek and the Sangamon River. The water table is at approximate depth of 180 feet beneath the facility (Visocky, et al., 1985). Soil borings performed on the east side of the facility encountered clay soils containing minimum ground water to the drilled depth of 31 feet.

2.7 RECEPTORS

The GE facility occupies 65 acres in a commercial area in Bloomington, Illinois. Bloomington has a population of about 45,000.

The GE facility is bordered on the north by commercial property and GE park, on the west by commercial property, on the south by commercial property, and on the east by vacant land. The nearest school, Stevenson School, is located about 0.5 miles south of the facility. Facility access is controlled by a north gate with a security guard present 24 hours a day, 7 days a week. There is also

a south gate that is kept locked. The entire site is secured by a 7-foot high, chain-link fence, with barbed wire on top.

The nearest surface water body, Sugar Creek, is located 0.2 mile north of the facility and is used for recreational purposes. Other surface water bodies in the area include Lake Bloomington, which is located 6 miles north of the GE facility.

Surface water from Lake Bloomington is used as the drinking water supply. There are no drinking water wells or industrial wells located within 3 miles of the facility.

Sensitive environments are not located on site. There are no wetland areas or sensitive environments located within 3 miles of the facility.

3.0 SOLID WASTE MANAGEMENT UNITS

This section describes the eight SWMUs identified during the PA/VSI. The following information is presented for each SWMU: description of the unit, dates of operation, wastes managed, release controls, history of documented releases, and RAI observations.

SWMU 1 Hazardous Waste Storage Area No. 1

Unit Description: The Hazardous Waste Storage Area is located indoors, in a room on

the east side of the facility. The unit stores hazardous waste for less than 90 days. The unit measures 15 feet by 20 feet and is made of ceramic tile over a concrete floor. The floor slopes up toward the

entrance (see Photograph No. 1). Floor drains are plugged in this

room.

Date of Startup: This unit began operation in mid-1991.

Date of Closure: This unit is active.

Wastes Managed: This unit manages wastewater treatment sludge (F006), waste paint

(F003/F005), paint sludge (D001), spent TCA (F001/F002), and spent

aerosol cans in containers. GE has not accumulated enough of the

spent aerosol cans to warrant disposal as yet. The wastewater

treatment sludge is picked up by Envirite of Harvey, Illinois for

reclamation of the metals. Waste paint and spent TCA are picked up

by Safety-Kleen of Dolton, Illinois for disposal. The paint sludge

(D001) is also picked up by Safety-Kleen of Dolton, Illinois for

incineration.

Release Controls: The unit is located indoors, on ceramic tile, over a concrete floor.

All floor drains are plugged in the room and the floor slopes up

toward the entrance.

History of Documented Releases:

No releases from this unit have been documented.

Observations:

The unit contained 31 closed 55-gallon steel drums and one cardboard 55-gallon drum during the VSI. No cracks were visible in the floor. The cardboard container stored spent aerosol cans. The rest of the drums contained paint waste (F003/F005), paint sludge (D001), wastewater treatment sludge (F006), and spent TCA (F001/F002). No evidence of release was noted.

SWMU 2

Nonhazardous Waste Storage Areas

Unit Description:

This unit consists of three Nonhazardous Waste Storage Areas that are located indoors. The first area is located in a room on the east side of the facility which stores nonhazardous waste. The area measures 10 feet by 20 feet and is made of ceramic tile over a concrete floor. The floor slopes up toward the entrance (see Photograph No. 2). The second area is located in the paint room, also on the east side of the facility. This area stores special waste polyester paint. The area measures 3 feet by 3 feet and is made of an 8-inch thick concrete floor. The floor slopes north to a drain for the Wastewater Treatment Unit (SWMU 3) (see Photograph No. 6). The third area is located in the grinding machine area of the facility. This area stores special waste grinding sludge. The moveable storage area is made of an open 90-gallon metal container (see Photograph No. 7).

Date of Startup:

This unit began operation in mid-1991.

Date of Closure:

This unit is active.

Wastes Managed:

This unit manages nonhazardous waste oil, waste coolant, and special waste polyester paint and grinding sludge in containers. The oil and

coolant wastes are picked up by Safety-Kleen. The waste coolant is fuel blended and the oil is recycled. The special wastes are picked up by CDI of Bloomington, Illinois, and disposed of at the Sexton-McLean County Landfill in Bloomington, Illinois.

Release Controls:

The unit is located indoors, on concrete. The floor drains are plugged in the room where waste oil and coolant are stored. The floor slopes up toward the entrance. In the area of the special waste polyester paint there is a floor drain to the north which leads to the Wastewater Treatment Unit (SWMU 3). There were no floor drains in the area of the grinding sludge.

History of Documented Releases:

No releases from this unit have been documented.

Observations:

The room where waste oil and coolant are stored contained 10 closed drums of nonhazardous waste oil and coolant during the VSI. No cracks were visible in the floor. No evidence of release was noted. In the area where special waste polyester paint is stored, one 55-gallon drum of polyester paint waste was observed during the VSI. No cracks were visible in the floor and no evidence of release was noted. The grinding sludge was stored in one 90-gallon container during the VSI. No cracks were visible in the floor and no evidence of release was noted.


SWMU 3

Wastewater Treatment Unit

Unit Description:

The Wastewater Treatment Unit is located indoors, in a room on the east side of the facility. The unit treats wastewater from the plating and painting processes. Wastewaters from these processes are gravity fed by pipe to the unit. There are three waste streams: (1) acid waste

stream, (2) cyanide, and (3) chromium. A process flow diagram of the Wastewater Treatment Unit is shown in Figure 3. The acid waste stream first enters a 10,000-gallon concrete receiving tank, which is inground, and then flows by gravity to another 10,000-gallon concrete tank for pH adjustment, where the precipitation process starts. The wastewater is then pumped to a 1,000-gallon fiberglass tank for further pH adjustment, and the precipitation process is finished. The wastewater is then pumped to a 650-gallon fiberglass flocculation tank. A gravity-fed line moves the wastewater from the flocculation tank to an 18,000-gallon steel clarifier tank. Clarifier overflow is then gravity fed and discharged into the sanitary sewer. Two to three times a week, the sludge is pumped out of the clarifier tank to a 5,000-gallon fiberglass sludge holding tank. The sludge is then pumped into a filter press to remove excess wastewater. The excess wastewater is pumped back to the second 10,000-gallon concrete pH adjustment tank in the acid waste stream. The wastewater treatment sludge (F006) is transferred from 1-cubic-yard steel dumpsters into a 20-cubic-yard roll-off box and stored at SWMU 8. The cyanide stream first enters a 1,000-gallon fiberglass receiving tank and is then pumped to a 10,000-gallon fiberglass holding tank. Redundant pumps move the wastewater to a 1,200-gallon fiberglass tank for cyanide destruction. The second pump is used as a backup in case the first pump fails. If this should occur, an alarm will sound and the second pump will move the wastewater to the 1,200-gallon cyanide destruction tank. If both pumps were to fail and the 10,000gallon holding tank overflowed, the wastewater would flow by gravity and discharge into the sanitary sewer. After the cyanide is destroyed, the wastewater is gravity fed to the second 10,000-gallon concrete pH adjustment tank in the acid waste stream. The chromium stream enters a 10,000-gallon concrete tank lined with acid resistant tile by



gravity-fed process lines. In this tank, the pH is adjusted. The wastewater is then pumped to a 500-gallon fiberglass chromium reduction tank. A treatment module with iron filings reduces the hexavalent chromium to trivalent chromium. The wastewater then flows by gravity-fed lines to the second 10,000-gallon concrete pH adjustment tank in the acid waste stream (see Photographs No. 3 and 4).

Date of Startup:

This unit began operation in mid-1955.

Date of Closure:

This unit is active.

Wastes Managed:

This unit manages wastewater and wastewater treatment sludge (F006) from the plating and painting processes. The treated wastewater is discharged into the sewer. The wastewater treatment sludge and spent filters (F006) are picked up by Envirite, Inc.

Release Controls:

The unit is located indoors, on the east side of the building. The unit consists of tanks and pits that have metal grating above them. There is a 6-inch concrete berm surrounding the initial acid waste stream, cyanide, and chromium receiving tanks.

History of Documented Releases:

No releases from this unit have been documented.

Observations:

The unit appeared clean and in good condition. There were no visible cracks in the floor. There were stains on the filter press, but no staining was visible on the floor in the area of the unit.

SWMU 4

Hazardous Waste Satellite Accumulation Areas

Unit Description:

The Hazardous Waste Satellite Accumulation Areas are located by the truck dock and in the paint room. The area by the truck dock is a metal 20-gallon container which accumulates spent aerosol cans. The area in the paint room accumulates used rags and gloves in a 15-gallon metal container (see Photographs No. 5 and 6).

Date of Startup:

This unit began operation in mid-1990.

Date of Closure:

This unit is active.

Wastes Managed:

This unit manages spent aerosol cans and hazardous nonreturnable gloves and rags contaminated with paint waste and setup paint (F003/F005). The waste paint is picked up by Safety-Kleen and incinerated.

Release Controls:

The unit is located indoors, on a concrete floor.

History of Documented

Releases:

No releases from this unit have been documented.

Observations:

During the VSI, the unit contained one 20-gallon container that accumulated spent aerosol cans. In the paint room, the unit contained hazardous gloves and towels (F003/F005) accumulating in one 15gallon container. No cracks were visible in the floor. No evidence of release was noted.

SWMU 5

Former Hazardous Waste Storage Area No. 1

Unit Description:

The Former Hazardous Waste Storage Area No. 1 is located outdoors in a 1,400-square-foot area. The unit slopes to the east and has partial curbing; it is made of an 8-inch thick concrete pad (see Photograph

No. 8).

Date of Startup: This unit began operation in mid-1980.

Date of Closure: This unit has been inactive since 1991 and is currently going through

closure.

Wastes Managed: This unit formerly managed: spent 1,1,1-trichloroethane (TCA)

(F001/F002), spent TCE (F001), spent naphtha (D001), spent

methylene chloride (F002), spent Freon (F001), spent ferric chloride

(D002), and wastewater treatment sludge (F006).

Release Controls: The unit is located outdoors, on the east side of the facility. The pad

is 8-inch thick concrete with a yellow gate and partial curbing

surrounding two sides.

History of Documented

Releases: Soil sampling performed in October 1991 determined that cadmium

was detected above the 1 mg/L TCLP level.

Observations: The unit was empty during the VSI. There were cracks in the

concrete pad. No evidence of release was noted.

SWMU 6 Former Hazardous Waste Storage Area No. 2

Unit Description: The Former Hazardous Waste Storage Area No. 2 is a concrete area

located outdoors, adjacent to the east side of the facility. The unit is approximately 40 feet by 12 feet with a canopy covering 60 percent of

the unit (see Photograph No. 9).

Date of Startup: This unit began operating in 1980.

Wastes Managed:

Date of Closure: This unit has been inactive since 1981 and is currently going through closure. This unit formerly managed: spent TCA (F001/F002), spent TCE Wastes Managed: (F001), spent naphtha (D001), spent methylene chloride (F002), spent Freon (F001), spent ferric chloride (D002), and wastewater treatment sludge (F006). Release Controls: The unit is located outdoors, adjacent to the east side of the facility. The area was covered with concrete. History of Documented Releases: Soil sampling performed in October 1991 revealed that TCE had contaminated the area around the unit. Facility representatives think that the contamination is from the January 24, 1991 spill, not from the waste that was managed at the unit. Observations: The unit was empty during the VSI. One crack in the concrete was visible. No visible evidence of release was noted. SWMU 7 Former Incinerator Unit Description: This unit was a solid waste incinerator located outdoors on the east side of the site. This unit measured approximately 20 feet by 20 feet (see Photograph No. 12). Date of Startup: This unit was installed in 1957. Date of Closure: This unit ceased operation in 1972 and was removed.

other nonhazardous waste.

This unit formerly incinerated office waste, boxes, wooden skids, and

Release Controls:

This unit is closed.

History of Documented

Releases:

Sampling was performed around this unit in October 1991. Cadmium

and lead were detected above TCLP levels.

Observations:

The unit is now a grassy swell on the east side of the site. No visual

evidence of release was observed during the VSI.

SWMU 8

Hazardous Waste Storage Area No. 2

Unit Description:

The Hazardous Waste Storage Area No. 2 is located outdoors, northeast of the facility. The unit stores hazardous waste in one 20-

cubic-yard roll-off box and concrete in two steel dumpsters. The unit measures 40 feet by 55 feet and has an 8-inch concrete pad (see

Photograph No. 10). No drains are located in the area.

Date of Startup:

This unit began operation in 1991.

Date of Closure:

This unit is active.

Wastes Managed:

The unit manages wastewater treatment sludge (F006), spent filters (F006), and concrete removed from the Trichloroethene Spill Area. The concrete is waiting for laboratroy analysis prior to disposal. Wastewater treatment sludge and spent filters are picked up by Envirite of Harvey, Illinois, for treatment by a pyrolitic recovery

technique to reclaim the metals.

Release Controls:

The unit is located outdoors, northeast of the facility. The pad is

made of 8-inch thick concrete.

History of Documented

Releases:

No releases from this unit have been documented.

Observations: The unit contained two steel dumpsters of excavated concrete waiting for disposal. No cracks were visible in the concrete pad.

4.0 AREA OF CONCERN

RAI identified one AOC during the PA/VSI. The AOC is discussed below; its location is shown in Figure 2.

AOC 1 Trichloroethene Spill Area

This area, located on the east side of the facility, was contaminated from the January 24, 1991, tank spill (see Photograph No. 11). Fifty cubic yards of soil were removed from the area, as well as the concrete overlying the soil. The soil was hauled off site by Peoria Disposal Company for disposal by Envirosafe Services of Ohio Inc., of Oregon, Ohio. The concrete remains on site pending laboratory analysis; it is being managed in two dumpsters (SWMU 8). Sampling performed in October 1991 revealed TCE contamination was still present in the soil. Harza Environmental Services, Inc. prepared a work plan proposing TCE investigation at the GE site for continuing remediation (GE, 1992a).

5.0 CONCLUSIONS AND RECOMMENDATIONS

The PA/VSI identified eight SWMUs and one AOC at the GE facility. Background information on the facility's location, operations, waste generating processes, history of documented releases, regulatory history, environmental setting, and receptors is presented in Section 2.0. SWMU-specific information, such as the unit's description, dates of operation, wastes managed, release controls, history of documented releases, and observed condition, is discussed in Section 3.0. The AOC is discussed in Section 4.0. Following are RAI's conclusions and recommendations for each SWMU and AOC. Table 3 identifies the SWMUs and AOC at the GE facility and recommended further actions.

SWMU 1 Hazardous Waste Storage Area

Conclusions: This area is located indoors and stores waste paint (F003/F005), paint sludge

(D001), spent TCA (F001/F002), and spent aerosol cans.

The unit has a low potential for release to ground water, surface water, air, and on-site soils. The unit has a ceramic tile floor over concrete with a berm at the entrance to the room. All floor drains are plugged in the room. Drums

are properly sealed.

Recommendations: RAI recommends no further action at this time.

SWMU 2 Nonhazardous Waste Storage Areas

Conclusions: The areas are located indoors and store nonhazardous waste oil, waste coolant,

and special waste polyester paint and grinding sludge.

The unit has a low potential for release to ground water, surface water, air, and on-site soils. The area that stores waste oil and coolant has ceramic tile over a concrete floor and floor drains are plugged. The area that stores special waste polyester paint has a concrete floor that slopes north to the

ENFORCEMENT CONFIDENTIAL

TABLE 3 SWMU AND AOC SUMMARY

<u>swmu</u>	Operational Dates	Evidence of Release	Suggested Further Action
Hazardous Waste Storage Area No. 1	1991 to present	None	No further action is suggested at this time.
2. Nonhazardous Waste Storage Areas	1991 to present	None	No further action is suggested at this time.
3. Wastewater Treatment Unit	1955 to present	None	No further action is suggested at this time.
4. Hazardous Waste Satellite Accumulation Areas	1990 to present	None	No further action is suggested at this time.
5. Former Hazardous Waste Storage Area No. 1	1980 to 1991	October 1991 soil sampling revealed cadmium contamination	Remediation of cadmium-contaminated soil.
6. Former Hazardous Waste Storage Area No. 2	1980 to 1981	October 1991 soil sampling revealed TCE contamination	Remediation of TCE-contaminated soil.
7. Former Incinerator	1957 to 1972	October 1991 soil sampling revealed cadmium and lead contamination	Remediation of cadmium and lead-contaminated soil.
8. Hazardous Waste Storage Area No. 2	1991 to present	None	No further action is suggested at this time.

ENFORCEMENT CONFIDENTIAL

TABLE 3

SWMU AND AOC SUMMARY CONTINUED

<u>AOC</u>	Operational Dates	Evidence of Release	Suggested Further Action
1. Trichloroethene Spill Area	1971 to present	January 24, 1991, 100 gallons of TCE	Continue remediation activities.

wastewater treatment unit drain. The area that stores the special waste grinding sludge has a concrete floor. Also, the wastes are nonhazardous.

Recommendations:

RAI recommends no further action at this time.

SWMU 3

Wastewater Treatment Unit

Conclusions:

The unit is located indoors and manages wastewater and wastewater treatment

sludge (F006) from the plating and painting processes.

The unit has a low potential for release to ground water, surface water, air, and on-site soils. The floor area is concrete and there is a 6-inch berm surrounding the initial receiving tanks. There is a gravity overflow to the

BNWRD from the 10,000-gallon cyanide holding tank.

Recommendations:

RAI recommends no further action at this time.

SWMU 4

Hazardous Waste Satellite Accumulation Areas

Conclusions:

The areas are located indoors and manage spent aerosol cans and waste paint

(F003/F005).

The unit has a low potential for release to ground water, surface water, air, and on-site soils. The containers are stored closed on a concrete floor.

Recommendations:


RAI recommends no further action at this time.

SWMU 5

Former Hazardous Waste Storage Area No. 1

Conclusions:

This unit is located outdoors, and previously stored spent TCA (F001/F002), spent TCE (F001), spent naphtha (D001), spent methylene chloride (F002), spent Freon (F001), spent ferric chloride (D002), and wastewater treatment



sludge (F006). The unit is currently undergoing closure for greater than 90-day storage. The unit has not stored waste since 1991.

Soil sampling in October 1991 revealed that cadmium was detected in on-site soil samples. Potential for release to surface water, ground water, and air is low, since the waste is no longer stored at this unit.

Recommendations: RAI recommends remediation of the cadmium-contaminated area.

SWMU 6 Former Hazardous Waste Storage Area No. 2

Conclusions: This unit is located outdoors, and previously stored spent TCA (F001/F002),

spent TCE (F001), spent naphtha (D001), spent methylene chloride (F002), spent Freon (F001), spent ferric chloride (D002), and wastewater treatment sludge (F006). The unit is currently undergoing closure for greater than 90

day storage. The unit has not stored waste since 1991.

Soil sampling was performed at SWMU 6 in October 1991. TCLP results

indicated TCE was detected in on-site samples. Potential for release to

ground water, surface water and air is low, since waste is no longer stored at

this unit.

Recommendations: RAI recommends the remediation of the TCE-contaminated soil.

SWMU 7 Former Incinerator

Conclusions: This unit was located outdoors, on the east side of the site. The unit

incinerated office waste and wood skids. It ceased operation in 1972 and was

later removed.

Soil sampling in October 1991 revealed that lead and cadmium were released to the soil. The level of contamination exceeded soil objectives set by IEPA

for closing SWMUs 5 and 6. Potential for release to ground water, surface water, and air is low, since waste is no longer stored at this unit.

Recommendations: RAI recommends remediation of the cadmium and lead-contaminated soil.

SWMU 8 Hazardous Waste Storage Area No. 2

Conclusions: This unit is located outdoors, and stores wastewater treatment sludge and

filters (F006) in a 20-cubic-yard roll-off box and two steel dumpsters of

concrete removed from the Trichloroethene Spill Area.

The unit has a low potential for release to ground water, surface water, air,

and on-site soils. The roll-off boxes are stored closed on an 8-inch concrete

pad.

Recommendations: RAI recommends no further action at this time.

AOC 1 Trichloroethene Spill Area

Conclusions: This area of soil is located on the east side of the facility that was

contaminated from the January 24, 1991, tank spill. Sampling performed in

October 1991 revealed TCE contamination was still present in the soil.

Recommendations: RAI recommends the facility continue remediation activities with IEPA

approval.

REFERENCES

- Bloomington and Normal Water Reclamation District (BNWRD), 1991. Discharge Permit, December 19.
- BNWRD, 1992. Conversation with Tom Brady of the Engineering Department, January 31.
- General Electric Company (GE), 1980a. Notification of Hazardous Waste Activity, August 11.
- GE, 1980b. RCRA Part A permit application, November 11.
- GE, 1985. Subsequent RCRA Part A permit application, January 26.
- GE, 1986. Subsequent RCRA Part A permit application, May 23.
- GE, 1991. Data Compilation and Review Report of Hazardous Waste Storage Facilities at GE by Harza Environmental Services, Inc., December.
- GE, 1992a. Proposed Work Plan of TCE investigation at GE, January 7.
- GE, 1992b. Map of facility obtained during VSI, January 24.
- GE, 1992c. Conversation with D.H. Sandahl, February 13.
- Illinois Environmental Protection Agency (IEPA), 1981. RCRA Inspection performed by IEPA, March 27.
- IEPA, 1983a. RCRA Inspection performed by IEPA, February 17.
- IEPA, 1983b. RCRA Inspection performed by IEPA, April 28.
- IEPA, 1984a. RCRA Interim Status Standards Inspection performed by IEPA, June 14.
- IEPA, 1984b. RCRA ISS Inspection performed by IEPA, December 20.
- IEPA, 1986. RCRA ISS Inspection performed by IEPA, February 27.
- IEPA, 1987. RCRA ISS Inspection performed by IEPA, August 28.
- IEPA, 1989. RCRA Land Disposal Restriction Inspection performed by IEPA, March 7.
- IEPA, 1990. Operating Air Permit, December 5.
- IEPA, 1991a. Approval of GE Closure Plan, June 12.
- IEPA, 1991b. RCRA ISS inspection performed by IEPA, September 27.

- Illinois Emergency Services and Disaster Agency (IESDA), 1991. Field Report of the trichloroethene spill, January 24.
- National Oceanic and Atmospheric Administration (NOAA), 1975. Climatography of the United States No. 20: Climate of Bloomington-Normal, Illinois.
- NOAA, 1990. Local Climatological Data: Peoria, Illinois.
- Stephenson, D.A., 1967. Hydrogeology of Glacial Deposits of the Mahomet Bedrock Valley in East-Central Illinois. <u>Illinois State Geological Survey Circular 409</u>, Urbana, Illinois.
- U.S. Department of Agriculture (USDA), 1992. Information provided by Soil Conservation Service Office, Bloomington, Illinois.
- U.S. Department of Commerce (USDC), 1968. <u>Climatic Atlas of the United States</u>, U.S. Government Printing Office, Washington, D.C.
- U.S. Geological Survey (USGS), 1981. Bloomington East Quadrangle, Illinois, 7.5-minute Topographical Series.
- Visocky, A.P., Sherril, M.G., and Cartwright, K., 1985. Geology, Hydrology, and Water Quality of the Cambrian and Ordovician Systems in Northern Illinois. Illinois State Geological Survey and Illinois State Water Survey Cooperative Groundwater Report 10; Urbana, Illinois.

ATTACHMENT A EPA PRELIMINARY ASSESSMENT FORM 2070-12



POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT

I. IDENTI	
O1 STATE	02 SITE NUMBER
iLD	005 453 691

	PART 1 - SITE INFORMA	ATION AN	D ASSESSME	NT	(4)	005 453 691
II. SITE NAME AND LOCATION Of SITE NAME (Legal, common, or descriptive name of site) 1 02 STREET, ROUTE NO., OR SPECIFIC LOCATION IDENTIFIER				·		
O1 SITE NAME (Legal, common, or descriptive name of General Electric Company - Electrical Distribution and (1801 GE F		H SPECIFIC LOCA	ION IDENTIFIER	
03 CITY		04 STATE	05 ZIP CODE	06 COUNTY	07 COUNTY	08 CONG
Bloomington		IL	61702	McLean	CODE	DIST
09 COORDINATES: LATITUDE	LONGITUDE		L		<u> </u>	
40 30 00.N	088 57 00.W	Ì				
10 DIRECTIONS TO SITE (Starting from nearest public						
•				1		
1 55 south to Business 55 (which is also called Veteran	s Parkway) to GE Road, make	a left (east)	on to GE Road,	and the facility is o	n the right.	
III. RESPONSIBLE PARTIES						
01 OWNER (if known)		02 STREET	(Business, maili	ng residential)		
General Electric Company		Appliance				
03 CITY Louisville		KY	05 ZIP CODE 40225	06 TELEPHONE (502) 452-4311	NUMBER	
07 OPERATOR (If known and different from owner)		1	(Business, mailin			
General Electric Company - Electrical Distribution and C	Control Division	1601 GE R		•		
09 CITY			11 ZIP CODE	12 TELEPHONE I	NUMBER	
Bloomington		IL.	61702	(309) 662-4311		
13 TYPE OF OWNERSHIP (Check one) A. PRIVATE D. B. FEDERAL:		пс	STATE	D. COUNTY	E. MUN	IICIPAL
	ency name)			_ 2		
D F. OTHER (Specify)		G. UNKI	NOWN			
	·~					
14 OWNER/OPERATOR NOTIFICATION ON FILE (Check	t all that apply)					
A. RCRA 3010 DATE RECEIVED: 11 / 11 MONTH DAY Y	·	WASTE SIT	TE (CERCLA 103	c) DATE RECEIVE	ED: / / MONTH DA	
IV. CHARACTERIZATION OF POTENTIAL HA	ZARD					
01 ON SITE INSPECTION BY (Check	t all that apply!					
□ A. EPA			C. STA	ATE D.	. OTHER CONTI	RACTOR
■ YES DATE 01 / 24 / 92 □ E. LOC	AL HEALTH OFFICIAL	F. OTH	R:	(Specify)		
				(Opechy)		
CONTRAC	CTOR NAME(S):Resource App	olications, In	ic			
02 SITE STATUS (Check one)	03 YEARS	OF OPERA	TION			
M A. ACTIVE D B. INACTIVE D C	. UNKNOWN	1955	Present		UNKNO	NWC
BEGINNING YEAR ENDING YEAR						
04 DESCRIPTION OF SUBSTANCES POSSIBLY PRES	ENT, KNOWN, OR ALLEGED			-		
Westes handled by GE are: waste paint, spent 1,1,1	-trichloroethane, weste oil ar	nd coolant	and arindina sluc	dae.		
05 DESCRIPTION OF POTENTIAL HAZARD TO ENVI	RONMENT AND/OR POPULA	TION				
A release of 100 gallons of trichloroethene to soil oc	curred on January 24, 1991,	and remedi	stion of the area	is currently in pro	ogress.	
Ouring closure activities for former hazardous waste	storage areas soil sampling in	October 15	391 revealed: tri	chioroethene, lead	f. and cadmium	contamination outside
•	•				,	
of the facility in the areas of the former incinerator and former hazardous waste storage areas.						
Currently there is a low potential of release from all 5	SWMUs to environmental med	dia at the si	te.			
V. PRIORITY ASSESSMENT						
OI PRIORITY FOR INSPECTION (Check one. If high or	medium is checked, complete	Part 2 - Was	te Information an	d Part 3 - Descripti	on of Hezerdous	Conditions and
Incidents.)						
D. A. HIGH D. B. MEDIUM D. C. LOW D. D. NONE (Inspection required promptly) (Inspection required) (Inspect on time-evailable basis) (No further action needed; complete current disposition form)						
(Inspection required promptly) (Inspection requ	irea) (inspect on time-	evapadie des	is) jivo turche	r action needed; co	enpiete current d	isposition formi
VI. INFORMATION AVAILABLE FROM						
01 CONTACT	02 OF (Agency/Organization)					03 TELEPHONE
VI GUITING!	on ingelicy/organization/					NUMBER
Kevin Pierard	EPA Region 5				1	(312) 886-4448
04 PERSON RESPONSIBLE FOR ASSESSMENT	05 AGENCY	06 ORGANI	ZATION	07 TELEPHONE N	UMBER	08 DATE
]
Laura Cząjkowski	{	Resource A	oplications, Inc.	(312) 332-2230		01 / 22 / 92 MONTH DAY YEAR

ATTACHMENT B VISUAL SITE INSPECTION SUMMARY AND PHOTOGRAPHS

VISUAL SITE INSPECTION SUMMARY

General Electric Company Bloomington, Illinois ILD 005 453 691

Date: January 24, 1992

Facility Representatives: Chris Boehm, Environmental Specialist

Paul Isabella, Plant Manager

Mark Sasek, Manager-Environmental, Health, & Safety

Inspection Team: Laura Czajkowski, Resource Applications, Inc. (RAI)

Peter McLaughlin, RAI

Photographer: Peter McLaughlin

Weather Conditions: Calm, sunny, temperature about 25°F.


Summary of Activities: The visual site inspection (VSI) began at 9:20 a.m. with an

introductory meeting. The inspection team discussed the purpose of the VSI and the agenda for the visit. Facility representatives then discussed the General Electric Company's (GE) past and current operations, solid wastes generated, and release history. Most of the information was exchanged on a question-and-answer basis. GE representatives provided the inspection team with copies of documents

requested.

The VSI tour began at 12:20 p.m. The definite purpose components assembly was the first area viewed. The next area viewed was machining and welding. The plating lines were then inspected followed by the hazardous and nonhazardous storage areas. The room containing the wastewater treatment unit was viewed next. The painting rooms were then toured and the area where the aqueous washer will be installed. The tour was then conducted outside and the two former hazardous waste storage areas, former incinerator, and the trichloroethene spill area were viewed.

The tour concluded at 2:30 p.m., after which the inspection team held an exit meeting with Chris Boehm, Paul Isabella, and Mark Sasek. The VSI was completed and the inspection team left the facility at 3:00 p.m.



Photograph No. 1 Location: SWMU 1
Orientation: North Date: 01/24/92

Description: Hazardous Waste Storage Area. Drums contain spent TCA (F001/F002), waste paint (F003/F005), spent aerosol cans (brown drum), and nonreturnable gloves and rag waste


(F003/F005).



Photograph No. 2 Location: SWMU 2
Orientation: North Date: 01/24/92

Description: Nonhazardous Waste Storage Area. Drums contain nonhazardous waste oil and


nonhazardous washer sludge.



Photograph No. 3
Orientation: North
Location: SWMU 3
Date: 01/24/92

Description: Wastewater Treatment Unit. Acid waste stream, chromium, and cyanide receiving

tanks.



Photograph No. 4 Orientation: East


Description: Filter press for Wastewater Treatment Unit

Location: SWMU 3 Date: 01/24/92



Photograph No. 5 Orientation: East Location: SWMU 4 Date: 01/24/92

Description: Hazardous Waste Satellite Accumulation Area of empty aerosol spray cans




Photograph No. 6 Orientation: East Location: SWMUs 4 and 2

Date: 01/24/92


Description: The red container accumulates waste rags and gloves (F003/F005-SWMU 4). The 55-

gallon drum stores special waste polyester paint (SWMU 2).



Photograph No. 7 Orientation: West Location: SWMU 2 Date: 01/24/92


Description: The 90-gallon metal container stores special waste grinding sludge.



Photograph No. 8 Orientation: East

Description: Former Hazardous Waste Storage Area No. 1

Location: SWMU 5 Date: 01/24/92




Photograph No. 9 Orientation: North

Description: Former Hazardous Waste Storage Area No. 2

Location: SWMU 6


Date: 01/24/92



Photograph No. 10 Location: SWMU 8
Orientation: Northeast Date: 01/24/92

Description: This is the Hazardous Waste Storage Area No. 2. The two steel dumpsters contain

concrete that was removed from the Trichloroethene Spill Area.



Photograph No. 11 Orientation: West

Description: Trichloroethene Spill Area

Location: AOC 1 Date: 01/24/92



Photograph No. 12
Orientation: East
Location: SWMU 7
Date: 01/24/92

Description: Site of the Former Incinerator, past the cement area and before the fence.

ATTACHMENT C VISUAL SITE INSPECTION FIELD NOTES

Bloomington 9:20am 300 employees the and shift at 30% manufacture industrial motors - assembly OF components thus place at the fresh Rice plant. 1955 manufacturing began
before that the land was farmland 24 hour quard security - 2 entrances -North and South N- conneccial property
E- vaccount land > Firmland 5- Commer cial property W- Corningral property. North about Comiles Lake Bloomington Northwest about 10 miles Late Eugegreen Skyenson School Markrost about 2 miles Nursey School on Deastly about Infile No wills on property. No NADES Permits Discharge water to sanutary sewer after treatment at Wasterbater Treatment Unit

GE Bloomington took zine niek.

JC 1/24/9

ijŁ.

GE Bloomington (Cold Plating Line - (Cold Room) gold-niebel plak 4 gold-flash - on bronze connectors - nichel plate phospharus bronze - the acid took - to date Qu drain that land from the room to the waste water tradinent with - and Concentrated acid are drained to the white to. The waste is neatralized & mutals reclaime J. final dip for gold plating - trichlowellme I drum of tool waste generaled once every 3 to mas when bash's are Cleaned. Plating Room -1) 100-line - a) electropolishing skinlesskel prophoric acid wash water drained 40 WWTU b) deuxidizing process & Al use mitric acid 4 hydrophloric ania C) passivastion of stainless Stel cleans and polishes skel use nitric acid 1/24/92

oc oraquisjon	
parts are then rinsed where flow going to water.	
a) 200 line - a) black + court oxide	
In oil - use stilling bydroxide	:
b) electropolisting strongsstell	
is no proprene and with early	
d) tumbling and burnishing oper.	†
e) zinc pating witank sodium ma	CXHL
3) 200-line 100 5010 dates	
a) clean pacts in allaline solution significant hudroxide & progrates	1
David dip tank sulfuria acid	2
c) Notating land Ni Chloride dit no dating land out	
en silver de le land sulfats	
population example	:

CE Blankington

GE Bloomington F. silver plak-lank postassium & silver cyanide.

rinse lanks

400-line zine planting line

a) alkaline cleaning tomk admin hydioxoe b) acid dip-lande Hel acid a) zinc plate tande - sertium hidroxide d) Final dip-land Chronode conversion coating hexaudent Cr + nitric acid 5) stoline - same as 400 line except brightness in dip tank Each line Contains a clear Cr tank withivalent Crd nitre and 6) 600 line - acid dipline for Zine direasting a) alkaline cleaning lank using sodium phosphode sodium our borrecte b) and dip teach - nitric hydrophlone do C) Chromode Conversion continghexavalent charmium with equip

Clear Christians acid with the contract acid Vapor dearrasor - Ten in room Benerales I acid whis will be eliminated by next month (February) will be replaced by an agueous Washer that is there; it has no next many Alter playing the parts move to assentibly. Painting a givens Boro electro cont use acryllice powder paints some solvents used - methane I. Jean 55005 - a. prespirale 3. Kinst sodium hydroxide	Clear Christicale vant - W/thirelent Continent acid Vapor degresor - Town in room generates I arim ext waste when Cleaned - this will be eliminated by next month the brown will be replaced by an argueous wasner that is there, it has do no installed. After playing the parts move to asson- bly: Painting & greas Book electro cont use acryllic powder paint bed - methane powder paint used - methane 1. Clean 5 stps - a prosphate 3 rints come solvents used - methane 2 prosphate 3 rints phosphating tank phosphatical acid waser soluble paint 3 to 40% organies	1- 1	20
Clear Christophade Jank - Withinedenth Continitore acid Vapor degrasor - Total in room generates I acum est weiste when Cleaned - Unis will be Eliminated by next month (February) will be replaced by an agueous washer that is there; it has John installed. After playing the parts move & assenting by, Painting & givens Day Day Painting & givens Day	Clear Christicale vant - W/thirelent Continent acid Vapor degresor - Town in room generates I arim ext waste when Cleaned - this will be eliminated by next month the brown will be replaced by an argueous wasner that is there, it has do no installed. After playing the parts move to asson- bly: Painting & greas Book electro cont use acryllic powder paint bed - methane powder paint used - methane 1. Clean 5 stps - a prosphate 3 rints come solvents used - methane 2 prosphate 3 rints phosphating tank phosphatical acid waser soluble paint 3 to 40% organies	GE Bloomination	Ì
Vapor degrasor - TCA in room generales I dain et waste when Cleaned - Hhis will be eliminated by next month Gebruay) will be replaced by an ague ous waster that is there, it has do he installed. After playing the parts move & asson- bly: Painting Q gives Painting Q gives powder paint use acyllic paints some solvents used methane 1. Clean 5 Steps - a prosphale a) kaline cleaner 2.	Vapor degrasor - TCA in room generates I acum est waste when Cleaned - Hhis will be eliminated by next month (February) will be replaced by an agueous waster that is there; it has to be installed. After planting the parts more to assembly: Painting a giveas Bodo electro cont use acryllic powder paint bed methane to hean 5 stops - a prosphale 3 rinse change paint prosphatic acid wader soluble paint 3 to 400 organes	Clear Chicomode tank - withought	
Cleaned - Units will be eliminated by next month (February) will be replaced by an agueous Washer that is there, it has have assentially. After planting the parts move & assentially. Painting & awas Painting & awas Poolo electro cont use acryllic paints powder print used methane 1. Clean 3. Prosphase Alkaline cleaner 2.	Cleaned - Hinis will be climinated by next ynouth Chebray) will be applaced by an agueous washer that is there, it has After playing the parts more & assan-bly. Painting & alreas Painting & alreas Boro electro cont use acryllice paints some solvents used - methane I. Jean Johnston	Vapor degrator - TCA in room	
eliminated by next month (February) will be replaced by an agus ous washer that is there; it has do he installed. After plating the parts move to assent bly: Painting Q givens every electro cont use acrylice powder paint bed methane some solvents used methane a prespirate alkaline cleaner consider solvents as a solvent of a solven	eliminated by next month (Februay) will be replaced by an ague ous waster that is there, it was so he installed. After phyting the parts move to asson- bly. Painting & givess good electro cont use acrylic paints some solvents used methane i. Clean 5 steps - a) kaline cleaner 3. rings waster solution hydroxide phosphatic acid waster solution paint 3 to 4 Pla organics waster solution paint 3 to 4 Pla organics		; -
Danting the parts move to assenting. Pointing Q givens Pointing Q givens Pointing Q givens Pointing Q givens Powder paint use acry///c paints some solvents used - methanic 1. Clean 2. Shops - a. prospinde a. kaline cleaner 3. Cinse sodium hydroxide	House what is there, it has do he installed. After playing the parts move & assenting the parts move & assenting. Painting & greas and use acrylle paints powder paints used methodic. I wear solvents used methodic. I wear solvents used methodic. I was prospered alkaline cleaner. 3 cinist addition paint 3 to 4% organics was acred.	eliminated by next month (Fetorium	1)
After playing the parts move & asson- bly. Pointing & givens Bond & givens List acryllice paints paints Some solvents used - methane 1. Clean 5 steps - alkaline cleaner 2.	After planting the parts prove & assembly. Painting & givens Book electro cont use acrylice powder paints Some solvents used - methanic a. prespirate a. prespirate Alle day School prespirates Constant prespirates Alle day Alle Alle da	Washer Huat is there, of has	
poolo electro cont use acrillic powder paint paints some solvents used methane	powder paint bed methane some solvents used methane a. prespirale 3. rinse while paint sodium hydroxide prespirates		541—
powder paint used methane. Lean 55/105 - a. prospiale alkaline cleaner. 2 2 2 3. Cinize sodium hydroxide.	powder paints used methate. 1. Clean 55-105 - alkaline Cleaner 2 3. Cinse solum hydroxide 2 4. dry prosprates paint 3-to 496 organies	(b) y ,-	
50me solvents used methanie 1. Clean 554ps - alkaline Cleaner 2. Sinse sodium hydroxide	Some solvents used - methanic. 1. Clean 3. Cinsc 3. Cinsc 4. dry 5. paint phosphorie acid wader soluble paint 3.10 496 crogonies	10 min na 0x giveas us acyllic	
a. prospince alkaline Cleaner.	1. Clean 2. Alkaline Cleaner 3. Cinta todium hydroxide 4. dry 5. pain + phosphotic acic phosphotic acic wader soluble pain + 3.10 496 crogenies		:
3 CMP 1 1 1 Dodum hydroxide	3. Cinox 4. dry 5. paint phosphorie acid phosphorie acid wader solubbe paint 3.10 496 crogonies		1'
	phosphoria acid	3. Cintal alkaline Cleaner 3. Cintal codium hydroxide	2
7, 0, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1,	water solubbe paint 3 to 42% progenies	77, G17	
phophoxic acic		photophorie acid	
Wolder Jahrole paint 3 to 4 Pla progenies	Ja 1/24/92 14.	work soluble paint 3 to 4 Pa organ	

GE Bloomington GE Bloomington DECout - 5,000 gallon diptank (conveyor) 2) paint shop - small parts are pouder inen allenine maleinet the cina goes unough we Clean phosphale lese epoxy or polymethane puder cont balang oven platini and Painting spray the paint on the baking even aprierates powder wase-(3) organic/solvent based painting all aciel alkaline moo of wast steam a generales solvent paint waste Cyanice bearing waste from 1) perider Coating -Tire the Coast Silvent blating a sero-trov hexava ent Chronium vinse all chemical tanks in painting are connected by drain to with From Chromode Conversion Carding point Shop - point strapping land to take off point from the

G.E. Boomington 2) Cyanide waste Steam - 5,000 gallon tente pH 0 FB. treatment module where agande is destroyed in oxiand Sodium hypo Chloride in the alkaline. Stream 1) the acid alkaline Edution - pt adjusted lowered from 8-106 10,000 gallon receiving tank then to a 10,000-gallon tende to adjust pH, the pH is adjusted to 6 and pecipitation process starts Dumped into a tank pH finally adjusted to 8.5 precipitation process finished all netals are now metallic hydroxides.

Out of foculation tank - act allowers into allowers where allowers we had allowers into allowers. tank Clarifier-18,000 realler tank metallic hydroxides settle to bottom the water is then discharged to

GE	Blamington
the POTW	and mixed with
monitored in	ater The walker is
1 24 hour ce	3 times a weekt =
discharge.	
Monitor	and for heavy maters
	Cyanide - Pob
	Susp Dollas
 - 	741
	Homs are removed
KAND KONDINGS	and a with a said
pumped mus	a filter press to we move
the water of the	
The 14175 (2)	e verroved but the
rolloff boxes	
-Osnerated, -	

GE. Bloomington Construction of receiving tanks hexavallent dank really a concrete pt lived w/ acid resistant tile Cyanide - concrete acid allaline - concrete Cyanide tank- Flourglass

PH - Flourglass

Clarifier - painted steel rinsing lank - Concrete - from Floor rinsings - periodically empties into acid alkaline Stream - every 4 to 5 mos le floor drains Chemical storage area for plating are 2 cm 3 drains There use up be a lab on six The plant in Kentucky took over their work for 5 years ago.

	GE. Bloomington
	miding - Hue moset blastic
	The moset - compression & misection
	Plantics come un poucher form - granules
/	thermosett - hert cone molding
(\ -	tunner coasil + granilaliedel
$\left\ \left({} \right. \right\ $	Huemopasta - Auntier Wiste
(some realigated
`	THE DE LE MAN LE DE LE MA CANTON
	transpix ha by - Sexten - onclean
	Commercial Disposal County Landfill, It
	agram ton a 235 vails to
	dry me lans reclaimed
	generation rate 20 wo 13 ft
_	Diecastina - Al low pressure diacistino,
	Very little waste - trimmed off
	parts are recovered.
	product comes in inpots.
	Ja 64342

Bleamington Separade barrels for All & Zn wask that will be recycled. Sheet metal Process-4-FX 10 FT sheets -> Hull Swilling uses a computer that efficiently uses the Whole Sheet The wask slugs go to reclyling low carbon steel bus bars - out of Cu- signegated of goes lo recepcler. Morris Ticle, local recycler of metal snap Machine Shop coil stock - stamp purts Strip stock phosphorous bronze brass Copper Steel all waste segregated a taken to recycler

Ar blo)	1
GE. Blocmineston	,
Huming Centers - bars -	
any what taken to recycler	
Waste oil- generated placed in draws	-
1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-	
rom splut tone side haz.	
3 areas of cleaning before	
machining and plating	
23 (1) Wato - a fev trachioing parts 23 (2) Wato - a few trachioing parts 24 (2) Wato - a few tracking parts 25 (2) Wato - a few tracking parts	
at a med then ment - a kaune hubber	•
Tall hous is acted parts are stained of oxer	
Heat teatment - Edum Car Drox	2.
TOA - WIN CE CERVACENTA,	
agueries consti washer	
Da (do 12/192	11.14

Pouler room - woder discharged to WWTa 1 horage avea (5) present storage began oper mid 1991 less than 90 day storage. 15x25 above (2) DP-1 mactive VL sed before 1980

(3) SP-2 inactive 1991 before 1984 skirkd / 30 x30 both units are undergoing chocure Now a large quantity generator May 1991 Closure plan approved June 12, 1991 - Should be Closed corretime this year. TCE spill January of 1997 100 gallons - Soil was due up 50 Cubic yards soil remand

GE. Bloomington 19772 Happed operating incineratori incinerated hendraz solidusasta trasta suds
performed soli sampling around even
teup Cd - below KORA they receive mend no factive tachon property on the east to builty NO USTS 1 UM 3/16 Tradire water tonks appregrand For Firesy Stem Sugar Creek Nor BE faci NET OF FOCULTY MONIMAGE LEVE

GE Bloomington 12:08 pm interview ended. 12:20 pm four Started DP comparents D East: Waste Silicon Steel from press 2) North parts washer (North and of building) 3) West steel studge - 90 gallon container 4) East Scrap nichal steel solid - 90 gallon Cont. 3) North petaleum naphtha parts washer 6 tast wask Cedant Lank - The waste is sumped into druin & Safety Kleen picks it is 250 gallons (1) East Scrap metal bacounulated & then piched up by local recycler. Icuarllon (8) East Spray Can disposal (9) West Gold form Secondary containment, a men bern (0) (5) North Hazardous washe slowed on right 32 drums 15 X20 stered closed weste lovels & naphthal agnosal Can dispusal Paint Wask

GE Bloomington
1 Lon hazardous Sherrage left
11110XDO 1101 Closed Acums 111
waste of stude
Floor 13 Certainie tile over coment
Floor decemps are plugger
(B) South
Plating vorm \$ 6.888 8 11 100 40 600
trench around lines - drains under
teaks that go to write
Pledure of Unencha grating
secondary containment conclus
B) North TCA Varox degreeser
(14) such east Cyande destroyer
AIKAUNE DESTIOYEN
3 Charite
(15) East
THER press hoppers w discharge
100 osillon steel dump sters
@ to causinoses+
Hebrarain where menitoring is
for 34192

GE Bloomington GE Bloomington (12) West Sludge helding lank B West Ward, Of print 23 Northeast sun lary sever (19) East olores et nonvoluinable rags
Wask polyurethane in one 55 galdies
From padder Caroling barolli. TOE Spill soil + concrok 25) East Former Haz weiste Storage 5/2 drain to www in Paint Room 30 North Mazard Wash Shoese SP area Where heales are cleaned liquid put directly into deam 27 West Tee spill area studies put into a bourset and Shipped to Hazardous Waste Storage once every 4 to 5 mes curbia contain. DE Cast area Peist at area all East East toxner in cinevator scrap plashe 30) East 2) Northwest proposed the a empty tanks 17 14 2 VVH | Evel (31) Will send discharge to With south leit trance to plant only below Outside 2.05 pm 北原 (72) 1/24/9/

CE Bloomington

Printing Press operation when the rollers on the press ove cleaned terme weedle rags are generated. they are put into the rag stream to be disposed ex.

four ended 2:30 pm.

Exit interview contact:


Mark Sasele (2x9) (do4-1445 06 CE is I have guastions

a Storm Sewer is located by the haz wast Storage aca inactive 15 parts degreaser in facility.

Je (73) 1/92

ATTACHMENT D

SOIL SAMPLING RESULTS FOR SWMUs 5, 6, AND 7



DATA COMPILATION AND REVIEW REPORT
HAZARDOUS WASTE STORAGE
FACILITIES
LPC No. 1130200016, McClean County
Bloomington, Illinois

HARZA

ENVIRONMENTAL SERVICES, INC. Consulting Engineers

December 1991

TABLE OF CONTENTS

	Page
1.0 INTRODUCTION AND BACKGROUND	1
2.0 SAMPLING AND ANALYSIS	3
2.1 Sampling Methods2.2 Analytical Parameters and Methods2.3 Summary of Results	3 4 5
2.3.1 Storage Pad SP-22.3.2 Storage Pad SP-12.3.3 Former Incinerator	5 6 6
3.0 SUMMARY AND CONCLUSIONS	8
3.1 Storage Pad SP-23.2 Storage Pad SP-13.3 Former Incinerator	8 8 9
TABLES	
FIGURES	
APPENDIX A. Laboratory Data	
 Volatile Organic Compounds Semi-Volatile Organic Compounds TCLP Metals, Reactivity and Corrosivity 	
APPENDIX B. Selected Photographs	

TABLES

- 1. Summary of Volatile Organic Analyses, Storage Pad SP-2
- 2. Summary of Semi-Volatile Organic Analyses, Storage Pad SP-2
- 3. Summary of TCLP Metals, Reactivity and Corrosivity Analyses, Storage Pad SP-2
- 4. Summary of Volatile Organic Analyses, Storage Pad SP-1
- 5. Summary of Semi-Volatile Organic Analyses, Storage Pad SP-1
- 6. Summary of TCLP Metals, Reactivity and Corrosivity Analyses, Storage Pad SP-1
- 7. Summary of Volatile Organic Analyses, Former Incinerator
- 8. Summary of TCLP Metals, Reactivity and Corrosivity Analyses, Former Incinerator

FIGURES

- 1. Site Location Map
- 2. Storage Pad No. 2, Sample Location Map (includes Former Incinerator Area)
- 3. Storage Pad No. 1, Sample Location Map

1.0 INTRODUCTION AND BACKGROUND

This report presents results of soil sampling conducted in October 1991 at the General Electric (GE) plant in Bloomington, Illinois. The sampling addressed two former hazardous waste storage pads and a former solid waste incinerator area. Sampling was conducted by Harza Environmental Services, Inc. (Harza) in accordance with the Revised Closure Plan of May 1, 1991. The Revised Closure Plan was submitted to the Illinois Environmental Protection Agency (IEPA) by Eldredge Engineering Associates, Inc. (EEA), and was approved with conditions by IEPA letter dated June 12, 1991.

The GE plant is located at 1601 GE Road, Bloomington, McClean County, Illinois (Figure 1). The property was acquired by GE in the 1950s and is operated by its Electrical Distribution and Control Division for the manufacture of electrical controls such as motor starters, solenoids and relays. Additional information on site conditions and history is provided in the Revised Closure Plan.

The storage pads and former incinerator area are located on the east side of the manufacturing building. Storage Pad 2 (SP-2) was used from about 1981 until recently as an interim status RCRA storage unit for hazardous wastes generated on-site (Figure 2). Wastes were removed by GE prior to soil sampling. Storage Pad 1 (SP-1) formerly was used for storage of hazardous wastes (Figure 3). Such use may have postdated promulgation of RCRA and, therefore, closure of this facility also is being required. However, no hazardous wastes have been stored at this location for many years. The solid waste incinerator was used well before 1980, apparently for burning non-hazardous plant trash. The incinerator is not thought to be a regulated facility under RCRA and no longer exists. The sampling was included to facilitate the overall program.

The purpose of sampling at the two storage pads was to verify sampling conducted by Environmental Assessment Services, Inc. (EAS) submitted previously to IEPA, and to determine the presence, if any, of soil contamination exceeding soil cleanup objectives. Soil cleanup objectives for this site were established by IEPA letter to GE dated October 26, 1990. Results will be used to identify requirements for final closure of the facilities. Sampling objectives at the former solid waste incinerator were to evaluate impacts on site soils, if any, due to prior use of the incinerator.

A chronological summary of reports and closure activities leading up to submission of the Revised Closure Plan was included in the Plan. The following updates that chronology:

January 29, 1990	Closure Plan prepared by Environmental Assessment Services, Inc. (EAS) submitted to IEPA for active hazardous waste storage area (SP-2).
April 27, 1990	IEPA letter to GE approves EAS Closure Plan with 18 conditions attached. The former hazardous waste storage area (SP-1) was required to be included.
June 1990	Closure Plan revised by EAS including both SP-1 and SP-2 and submitted to IEPA. Additional waste stream information was provided to IEPA.
June 19 to 21, 1990	EAS conducts sampling proposed in the June 1990 Closure Plan, but not yet approved by IEPA. Program included collection and analysis of 66 samples.
July 1990	EAS summary of analytical results submitted to IEPA.
September 12, 1990	IEPA letter approves revised (June 1990) Closure Plan with 16 conditions attached.
October 26, 1990	IEPA letter to GE acknowledges receipt of EAS sampling data, indicates that sampling protocol was incorrect and requests a revised Closure Plan. Eleven conditions are attached. Soil cleanup objectives were established.
March 25, 1991	Eldredge Engineering Associates, Inc. (EEA) letter to IEPA requests extension until May 1, 1991 to submit revised Closure Plan. Extension request verbally accepted by IEPA.
May 1, 1991	Revised Closure Plan submitted to IEPA by EEA.
June 12, 1991	IEPA letter approves Revised Closure Plan with 13 conditions attached.
October 30 and 31, 1991	Harza implements revised sampling and analyses plan including collection and analysis of 26 samples at 13 locations.
December 30, 1991	Harza submits results of sampling and analysis (herein).

2.0 SAMPLING AND ANALYSIS

Soil samples were collected from thirteen (13) locations during this program, five (SP1-1 through SP1-5) from storage pad SP-1, six (SP2-1 through SP2-6) from SP2, and two (FI1 and FI2) from the former incinerator area. Samples were collected in shallow borings drilled through any concrete pavement and fill and into native soils. Locations are shown on Figure 2 for the SP-2 pad and former incinerator and Figure 3 for the SP-1 pad. Analytical data are provided in Appendix A and summarized in Section 2.3. Selected photographs taken during the sampling are provided in Appendix B.

2.1 Sampling Methods

Concrete coring and soil borings were performed by Testing Service Corporation (TSC) of Carol Stream, Illinois, monitored by Harza. Soil samples were screened by Harza using an HNU PI-101 photoionization detector, which measures total organic vapors. The HNU was fitted with an 11.7 eV lamp and was calibrated daily to a benzene equivalent. No HNU readings above background (zero) were detected.

Soil samples were collected by Harza in two basic depth intervals below the top of native soil: 0 to 6 inches and 18 to 24 inches. This depth interval was specified in the IEPA letter dated June 12, 1991. All sample depths were measured from the top of the native soil surface below the concrete pad, except for SP2-6, FI-1 and FI-2, which were located on grassy areas. For these locations, soil samples were collected at depths of 6 to 12 inches and 18 to 24 inches as required by IEPA's letter. Due to poor sample recovery and difficulties encountered in advancing the sampler, the depth of two of the deeper samples (SP1-1-2 and SP1-5-2) was adjusted slightly to the 24 to 30 inch depth interval.

Sample designations consist of the feature designation (i.e. SP1, SP2 or FI), location number (i.e. "1", "2", etc.), and sample depth ("1" indicates the shallower sample and "2" the deeper sample at each location). For example, sample SP1-1-2 was collected from Storage Pad 1, location 1 at the 18 to 24 inch depth interval.

A five-inch diameter, diamond-tipped core barrel was used to core through the concrete pad and gain access to the underlying subbase and soil materials. The shallower soil samples were then collected by pushing a precleaned, ten-inch long, stainless steel, thin-walled tube (Shelby Tube), six inches into the soil. After collection of this sample, the hole was advanced to a depth of 18 inches and a second ten-inch tube was pushed to collect the deeper sample. After completion of sampling, the holes were backfilled with pea gravel and patched with concrete in pad areas.

Three locations, SP1-3, SP1-4 and SP1-5, were located under a canopy which precluded drill rig access. For these, the hole was advanced using a stainless steel bucket hand auger. At two locations, SP1-1 and SP2-3, insufficient sample quantity was obtained from the original hole to perform required analyses. Therefore, at these locations a new hole was drilled immediately adjacent to the original, and the required sample quantities were obtained at appropriate depths. Sample SP1-1-1 was obtained from the original hole (SP1-1), and SP1-1-2 from the redrilled hole (SP1-1A). Sample SP2-3-1 was obtained from the redrilled hole (SP2-3A), and SP2-3-2 was obtained from the original hole (SP2-3). These samples were collected as part of the same sampling event and utilized the same sampling procedures.

Upon extraction of the tubes from the soil, additional clean clay was added to the headspace portions at each end. The tube then was capped and stored in a chilled cooler. The samples were delivered to the laboratory via overnight courier. The stainless steel Shelby Tubes had been precleaned in accordance with Attachment 1 of IEPA's "Instructions for the Preparation of Closure Plans for Interim Status RCRA Hazardous Waste Facilities." The sequence for cleaning the tubes was:

- 1. Wash with hot water and non-foaming detergent.
- 2. Rinse with hot water.
- 3. Rinse with methanol, recommended by the laboratory.
- 4. Rinse with hot water.
- 5. Rinse with deionized water.

The tubes then were wrapped in aluminum foil until needed.

Two rinsate blanks were collected by pouring deionized water over the precleaned tubes and collecting the rinsate in sample bottles. Two trip blanks also were prepared, consisting of deionized water poured into sample containers by the laboratory and shipped to Harza with the other containers. The trip blanks were present at the site during sampling and were shipped to the laboratory with the samples.

2.2 Analytical Parameters and Methods

Laboratory analyses were performed by Applied Research and Development Laboratory (ARDL), of Mt. Vernon, Illinois. ARDL is a member of the IEPA Contract Laboratory Program. Analytical parameters and methods were in accordance with the Work Plan, as approved by IEPA. Parameters and SW-846 methods used were:

Volatile Organics Method 8240
Semi-Volatile Organics Method 8270
TCLP Metals Method 1311
Corrosivity Method 9045
Reactive Cyanide Section 7.3.3.2

All soil samples were analyzed for volatile organics, TCLP metals, corrosivity (soil pH), and reactive cyanide. Semi-volatile analyses were obtained for the upper sample from each location at the SP-1 and SP-2 storage pad areas. Semi-volatile analyses were not required for the deeper samples or for the former incinerator area, in accordance with IEPA's June 12, 1991 approval letter. The field rinsate blanks were analyzed for VOCs and nine metals (arsenic, barium, cadmium, chromium, lead, mercury, nickel, selenium and silver). The trip blanks were analyzed for VOCs. Additional information on analytical protocols and Quality Control results are provided in the Case Narratives included in Appendix A.

2.3 Summary of Results

Results of analyses are summarized in the following sections with reference to Tables 1 through 8, Figures 2 and 3, and Appendix A. Results are compared to Class II Soil Objectives, where available, listed in IEPA's letter to GE dated October 26, 1990. Where applicable, comparisons also are made to proposed RCRA Corrective Action levels as provided in USEPA's Proposed Rule "Corrective Action for Solid Waste Management Units (SWMUs) at Hazardous Waste Management Facilities" (EPA/SW-530-90-012, July 1990). Results of analyses for reactive cyanide and corrosivity are included in the tables and Appendix A, but are not summarized in the text because they apply to possible disposal requirements. Selected site photographs are included in Appendix B.

2.3.1 Storage Pad SP-2

Results of VOC analysis from SP-2 are summarized in Table 1. No VOCs were detected above IEPA's Class II Soil Objectives. Only acetone and xylene, near the Contract Required Detection Limit (CRDL) and well below soil objectives, were positively identified in any sample. Acetone also was detected in the blank sample.

Results of semi-volatile analysis from SP-2 are summarized in Table 2. No site soil objectives are available for these parameters. The only semi-volatiles positively identified were bis(2-ethylhexyl)phthalate in each sample and the blank, 2-

methylphenol and 4-methylphenol below the CRDL in SP2-6-1, and 4-chloro-3-methylphenol below the CRDL in SP2-2-1. Bis(2-ethylhexyl)phthalate concentrations were also below the CRDL in all but one sample.

Table 3 summarizes results of TCLP metals analysis from SP-2. Only TCLP cadmium was found to exceed available IEPA soil objectives and was detected in all samples except SP2-4-1 and SP2-6-2. Where detected, concentrations exceeded IEPA's soil objective of 0.05 mg/L except at SP2-4-2. Several results (SP2-1-1, SP2-2-1, SP2-2-2, SP2-5-1 and SP2-5.2) also exceeded the RCRA characteristic regulatory level of 1.0 mg/L. No other TCLP metals were found to exceed available soil objectives and arsenic, nickel and selenium were not detected in any sample.

2.3.2 Storage Pad SP-1

Results of VOC analyses from SP-1 are summarized in Table 4. Only trichloroethene (TCE) exceeded available site soil objectives and few other VOCs were detected in any sample. TCE occurrences were limited to the south half of the SP-1 pad and concentrations, ranging between 25 and 120 ug/kg, increased toward the south. All results were well below the proposed RCRA Action Level of 60,000 ug/kg.

Results of semi-volatile organic analyses from SP-1 are summarized in Table 5. No soil objectives are available for semi-volatiles. Bis(2-ethylhexyl)phthalate was found near or below the CRDL in each sample and in the blank. The only other semi-volatiles positively identified were fluoranthene and pyrene in SP1-1, both below the CRDL.

Table 6 summarizes results of TCLP metals analysis from SP-1. No TCLP metals were found to exceed available soil objectives and no arsenic, chromium, lead, nickel or selenium were detected in any sample.

2.3.3 Former Incinerator

Results of VOC analyses from the former incinerator area are summarized in Table 7. No VOCs were detected above available soil objectives. Only acetone, toluene and trichloroethene were positively identified in any sample, all well below their respective soil objectives and at or below the CRDL. Acetone also was found in the blank.

Table 8 summarizes results of TCLP metals analysis from the former incinerator. Only TCLP cadmium at location FI-2 and lead in sample FI-2-1 were found to slightly exceed available soil objectives.

3.0 SUMMARY AND CONCLUSIONS

3.1 Storage Pad SP-2

TCLP cadmium is the only parameter found to exceed available IEPA soil objectives at the SP-2 Storage Pad. No other organic or TCLP parameters were found to exceed soil objectives established for the site by IEPA and no semi-volatiles above the CRDL were confirmed.

The six-inch thick concrete pavement presently covering the SP-2 area minimizes direct contact with the affected soils, while inhalation is not an exposure route of concern for cadmium. Access to the site is controlled by plant security and fencing and the site is used only for activities directly related to GE manufacturing operations (i.e. truck deliveries, equipment storage, parking, maintenance, etc.). The concrete pavement also reduces the quantity of precipitation which might infiltrate into the affected soils, thereby reducing the likelihood that cadmium will migrate beyond the immediate pad area or to groundwater. Due to their low hydraulic conductivity and tendency to adsorb metallic ions, the dense, clayey till soils underlying the pavement further reduce the rate at which precipitation can infiltrate through the affected soils and, therefore, the likelihood that cadmium will migrate. Cadmium also is relatively insoluble in water at normal pH levels. Groundwater itself is not indicated to be an issue because the clay tills immediately underlying the site contain little free groundwater and are not suitable for water supply development due to low yields. Test pits and borings, completed for unrelated purposes to the east, encountered only clay soils containing little groundwater to the maximum excavated or drilled depth of 31 feet.

Based on these site conditions, cadmium in soils at SP-2 is suggested to offer little exposure and, therefore, risk to human health and minimal potential for migration and adverse environmental impacts. Closure of SP-2 as a RCRA hazardous waste storage facility could be achieved by leaving the affected soils in place and maintaining the existing concrete pavement as a cap. The effectiveness of the pavement as a cap would be enhanced by sealing the surface, including any cracks, and further promoting surface water runoff by breaching the existing curbing. Controls also should be implemented to assure future maintenance of the pavement and preclude disturbance or alternative use.

3.2 Storage Pad SP-1

TCE is the only parameter of apparent concern at the SP-1 storage pad. TCE was not detected in the north part of the pad, but exceeded IEPA's soil objective in the south

part of the area, increasing in concentration toward the south. The maximum concentration (120 ug/kg) remained well below USEPA's proposed RCRA Corrective Action Level for soil (60,000 ug/kg) and no other soil objectives were exceeded.

The pattern of TCE occurrence at SP-1 indicates that the contamination is not related to use of the storage pad itself, which ceased by the early 1980s, but is due to a more recent release from an adjacent TCE tank area to the southwest. Although no longer active and not part of this RCRA closure, the TCE tank area is the subject of ongoing assessment and remedial efforts reported separately to IEPA (Emergency Response Unit, Office of Chemical Safety, Incident 910226). To date, these efforts have included soil sampling and screening, removal of the TCE tank, removal of concrete paving, and disposal of about 50 cubic yards of contaminated soil. This effort is incomplete and the extent of contamination is not fully known. However, available data indicate it extends toward the SP-1 pad and plans for further assessment are being developed.

The sampling results indicate no soil contamination apparently attributable to past or present use of the SP-1 storage pad. From this perspective, therefore, no further actions appear necessary for its closure as a RCRA hazardous waste storage facility. However, contamination beneath the TCE tank area will have to be addressed, including the south half of the SP-1 pad, as appropriate. This can be accomplished effectively only as an integrated program which appears separate from the SP-1 closure. Plans for further investigation leading to remediation of the TCE tank area are being developed and will be submitted to the Emergency Response Unit of the IEPA.

3.3 Former Incinerator

No hazardous wastes are known to have been burned in the former incinerator and, therefore, it is not thought to be a RCRA facility. Sampling was included only as a cost-effective means of evaluation. However, IEPA soil objectives applied to the RCRA closures at SP-1 and SP-2 provide useful comparative values. TCLP cadmium in both samples and lead in the deeper sample at location FI-2 are the only parameters indicated to exceed the soil objectives. Each is well below RCRA characteristic regulatory levels and no other TCLP metals or organics are indicated to be of concern. Based on these results, past operation of the incinerator does not appear to have had significant adverse impact on the environment and currently poses little risk to human health. The incinerator has been removed and further actions appear unnecessary.

TABLES

SUPPLEMENTAL NOTES TO TABLES

- "J" Indicates an estimated value. This flag is used either when estimating a concentration for TICs where a 1:1 response is assumed or when the mass spectral data indicate the presence of a compound that meets the identification criteria but the result is less than the CRDL.
- "B" This flag is used when the analyte is found in the blank as well as the sample. This flag must be used for a TIC as well as for a positively identified TCL compound.
- '<" Indicates parameter not detected at the concentration shown.
- "•" Indicates unknown compounds detected in sample. See Appendix A.
- NA Not available.

TABLE 1 (Page 1 of 2)
Summary of Volatile Organic Analyses, Storage Pad SP-2
General Electric Company, Bloomington, Illinois

D	SP2-1-1*	SP2-1-2*	SP2-2-1*	Sample Nu SP2-2-2	mber ¹ SP2-3-1*	SP2-3-2*	SP2-3-2RE*	IEPA Site Objectives	Units
Parameter	352-1-1	31 4-1-4	312-2-1	31 2-2-2	312-3-1	J12-J-2	31 2-3-2 KD	Conjectives	Oints
Acetone	13 B	13 B	19 B	35 B	7 JB	< 12	< 12	700	ug/Kg
Benzene	<6	<6	<6	<6	<6	<6	<6	NA	ug/Kg
Bromodichloromethane	<6	<6	<6	<6	<6	<6	<6	NA	ug/Kg
Bromoform	<6	<6	<6	<6	<6	<6	<6	NA	ug/Kg
Bromomethane	< 12	< 12	< 12	<11	<13	<12	<12	NA	ug/Kg
2-Butanone	< 12	< 12	< 12	<11	< 13	<12	<12	NA	ug/Kg
Carbon Disulfide	<6	<6	<6	<6	<6	<6	<6	NA	ug/Kg
Carbon Tetrachloride	<6	<6	<6	<6	<6	<6	<6	NA	ug/Kg
Chlorobenzene	<6	<6	<6	<6	<6	<6	<6	NA	ug/Kg
Chloroethane	< 12	< 12	< 12	<11	<13	< 12	< 12	NA	ug/Kg
Chloroform	<6	<6	<6	<6	<6	<6	<6	NA	ug/Kg
Chloromethane	< 12	< 12	< 12	< 11	< 13	< 12	<12	NA	ug/Kg
Methylene Chloride	<6	<6	<6	<6	<6	<6	<6	25	ug/Kg
Dibromochloromethane	<6	<6	<6	<6	<6	<6	<6	NA	ug/Kg
1,1-Dichloroethane	<6	<6	<6	<6	<6	<6	<6	NA	ug/Kg
1,2-Dichloroethane	<6	<6	<6	<6	<6	<6	<6	1,000	ug/Kg
1,1-Dichloroethene	<6	<6	<6	<6	<6	<6	<6	35	ug/Kg
1,2-Dichloroethene (total)	<6	<6	<6	<6	<6	<6	<6	700	ug/Kg
1,1,1-Trichloroethane	<6	<6	<6	<6	<6	<6	<6	NA	ug/Kg
1,1,2-Trichloroethane	<6	<6	<6	<6	<6	<6	<6	NA	ug/Kg
1,2-Dichloropropane	<6	<6	<6	<6	<6	<6	<6	NA	ug/Kg
cis-1,3-Dichloropropane	<6	<6	<6	<6	<6	<6	<6	NA	ug/Kg
trans-1,3-Dichloropropane	<6	<6	<6	<6	<6	<6	<6	NA	ug/Kg
Ethylbenzene	<6	<6	<6	<6	<6	<6	<6	1,000	ug/Kg
2-Hexanone	< 12	< 12	<12	<11	<13	< 12	<12	NA	ug/Kg
4-Methyl-2-Pentanone	< 12	< 12	< 12	<11	<13	<12	<12	NA	ug/Kg
Styrene	<6	<6	<6	<6	<6	<6	<6	NA	ug/Kg
Tetrachloroethene	<6	<6	<6	<6	<6	<6	<6	NA	ug/Kg
1,1,2,2-Tetrachloroethane	<6	<6	<6	<6	<6	<6	<6	NA	ug/Kg
Toluene	<6	<6	<6	<6	<6	<6	<6	5,000	ug/Kg
Trichloroethene	<6	<6	<6	<6	<6	<6	<6	25	ug/Kg
Vinyl Acetate	<12	< 12	<12	<11	<13	<12	<12	ND	ug/Kg
Vinyl Chloride	<12	< 12	< 12	<11	<13	<12	<12	10	ug/Kg
Xylene (total) Ethylmethylbenzene ²	<6 -	<6 -	<6 -	6 33	<6 -	<6 -	<6 -	10,000 NA	ug/Kg ug/Kg

TABLE 1 (Page 2 of 2)
Summary of Volatile Organic Analyses, Storage Pad SP-2
General Electric Company, Bloomington, Illinois

				Sample Nu	mber ¹		IEPA Site		
Parameter	SP2-4-1*	SP2-4-2	SP2-5-1	SP2-5-2	SP2-6-1*	SP2-6-2*	Objective	Units	
Acetone	< 12	14 B	9 JB	12	17 B	16 B	700	ug/Kg	
Benzene	<6	<6	<6	<6	<6	<7	NA	ug/Kg	
Bromodichloromethane	<6	<6	<6	<6	<6	<7	NA	ug/Kg	
Bromoform	<6	<6	<6	<6	<6	<7	NA	ug/Kg	
Bromomethane	< 12	< 12	< 12	<11	< 13	< 14	NA	ug/Kg	
2-Butanone	< 12	< 12	< 12	<11	<13	< 14	NA	ug/Kg	
Carbon Disulfide	<6	<6	<6	<6	<6	<7	NA	ug/Kg	
Carbon Tetrachloride	<6	<6	<6	<6	<6	<7	NA	ug/Kg	
Chlorobenzene	<6	<6	<6	<6	<6	<7	NA	ug/Kg	
Chloroethane	< 12	< 12	< 12	<11	< 13	< 14	NA	ug/Kg	
Chloroform	<6	<6	<6	<6	<6	<7	NA	ug/Kg	
Chloromethane	< 12	< 12	< 12	<11	< 13	< 14	NA	ug/Kg	
Methylene Chloride	<6	<6	<6	<6	<6	<7	25	ug/Kg	
Dibromochloromethane	<6	<6	<6	<6	<6	<7	NA	ug/Kg	
1,1-Dichloroethane	<6	<6	<6	<6	<6	<7	NA	ug/Kg	
1,2-Dichloroethane	<6	<6	<6	<6	<6	<7	1,000	ug/Kg	
1,1-Dichloroethene	<6	<6	<6	<6	<6	<7	35	ug/Kg	
1,2-Dichloroethene (total)	<6	<6	<6	<6	<6	<7	700	ug/Kg	
1,1,1-Trichloroethane	<6	<6	<6	<6	<6	<7	NA	ug/Kg	
1,1,2-Trichloroethane	<6	<6	<6	<6	<6	<7	NA	ug/Kg	
1,2-Dichloropropane	<6	<6	<6	<6	<6	<7	NA	ug/Kg	
cis-1,3-Dichloropropane	<6	<6	<6	<6	<6	<7	NA	ug/Kg	
trans-1,3-Dichloropropane	<6	<6	<6	<6	<6	<7	NA	ug/Kg	
Ethylbenzene	<6	<6	<6	<6	<6	<7	1,000	ug/Kg	
2-Hexanone	<12	<12	<12	<11	<13	< 14	NA	ug/Kg	
4-Methyl-2-Pentanone	<12	<12	< 12	<12	<13	< 14	NA	ug/Kg	
Styrene	<6	<6	<6	<6	<6	<7	NA	ug/Kg	
Tetrachloroethene	<6	<6	<6	<6	<6	<7	NA	ug/Kg	
1,1,2,2-Tetrachloroethane	<6	<6	<6	<6	<6	<7	NA	ug/Kg	
Toluene	<6	<6	<6	<6	<6	<7	5,000	ug/Kg	
Trichloroethene	<6	<6	<6	<6	<6	<7	25	ug/Kg	
Vinyl Acetate	< 12	< 12	< 12	<11	<13	<14	ND	ug/Kg	
Vinyl Chloride	< 12	<12	<12	<11	< 13	<14	10	ug/Kg	
Xylene (total)	<6	<6	<6	<6	<6	<7	10,000	ug/Kg	
1,1,2-Trichloro-1,2,2-trifluoroethane		13	-	11	•	12	NA	ug/Kg	

NOTES: 1. See Figure 2 for sample locations and Appendix A for laboratory reports. See attached Supplemental Notes.

- 2. Tentatively identified compound (TIC). Concentration estimated.
- 3. Sample SP2-3-2 reanalyzed by laboratory (SP2-3-2RE). See Appendix A.

TABLE 2 (Page 1 of 2)
Summary of Semi-Volatile Organic Analyses, Storage Pad SP-2
General Electric Company, Bloomington, Illinois

			Sample	Number ¹			
Parameter	SP2-1-1	SP2-2-1	SP2-3-1	SP2-4-1	SP2-5-1	SP2-6-1	Units
Phenol	<390	<400	<430	<380	<400	<420	ug/Kg
bis(2-Chloroethyl)ether	< 390	<400	<430	<380	< 400	< 420	ug/Kg
2-Chlorophenol	< 390	< 400	< 430	<380	< 400	< 420	ug/Kg
1,3-Dichlorobenzene	< 390	< 400	< 430	< 380	< 400	< 420	ug/Kg
1,4-Dichlorobenzene	< 390	< 400	< 430	<380	< 400	< 420	ug/Kg
Benzyl alcohol	< 390	<400	< 430	<380	< 400	< 420	ug/Kg
1,2-Dichlorobenzene	< 390	< 400	< 430	<380	< 400	< 420	ug/Kg
2-Methylphenol	< 390	< 400	<430	< 380	<400	390 J	ug/Kg
bis(2-chloroisopropyl)eth	er < 390	< 400	< 430	< 380	< 400	< 420	ug/Kg
4-Methylphenol	< 390	<400	<430	<380	< 400	290 J	ug/Kg
N-Nitroso-Di-n-propylam	ine < 390	< 400	< 430	< 380	< 400	< 420	ug/Kg
Hexachloroethane	< 390	< 400	< 430	<380	< 400	< 420	ug/Kg
Nitrobenzene	< 390	< 400	< 430	< 380	< 400	< 420	ug/Kg
Isophorone	< 390	< 400	<430	< 380	< 400	< 420	ug/Kg
2-Nitrophenol	< 390	< 400	<430	< 380	< 400	<420	ug/Kg
2,4-Dimethylphenol	< 390	< 400	<430	< 380	< 400	< 420	ug/Kg
Benzoic acid	< 1,900	< 1,900	< 2,100	< 1,900	< 2,000	< 2,000	ug/Kg
bis(2-Chloroethoxy)metha	ane < 390	< 400	<430	< 380	< 400	< 420	ug/Kg
2,4-Dichlorophenol	< 390	< 400	< 430	< 380	< 400	< 420	ug/Kg
1,2,4-Trichlorobenzene	< 390	< 400	<430	< 380	< 400	< 420	ug/Kg
Naphthalene	< 390	< 400	<430	< 380	< 400	< 420	ug/Kg
4-Chloroaniline	< 390	< 400	<430	<380	< 400	< 420	ug/Kg
4-Hexachlorobutadiene	< 390	< 400	< 430	< 380	< 400	< 420	ug/Kg
4-Chloro-3-methylphenol	< 390	380 J	< 430	< 380	< 400	< 420	ug/Kg
2-Methylnaphthalene	< 390	< 400	< 430	< 380	< 400	< 420	ug/Kg
Hexachlorocyclopentadier	ne < 390	< 400	< 430	< 380	< 400	< 420	ug/Kg
2,4,6-Trichlorophenol	< 390	< 400	< 430	<380	< 400	< 420	ug/Kg
2,4,5-Trichlorophenol	< 1,900	< 1,900	< 2,100	< 1,900	< 2,000	< 2,000	ug/Kg
2-Chloronaphthalene	< 390	< 400	<430	< 380	<400	<420	ug/Kg
2-Nitroaniline	< 1,900	< 1,900	< 2,100	< 1,900	< 2,000	< 2,000	ug/Kg
Dimethylphthalate	< 390	< 400	<430	<380	< 400	< 420	ug/Kg
Acenaphthylene	< 390	< 400	<430	<380	< 400	< 420	ug/Kg
2,6-Dinitrotoluene	< 390	< 400	< 430	<380	< 400	< 420	ug/Kg
3-Nitroaniline	< 1,900	< 1,900	< 2,100	< 1,900	< 2,000	< 2,000	ug/Kg
Acenaphthene	< 390	< 400	< 430	<380	< 400	< 420	ug/Kg
2,4-Dinitrophenol	< 1,900	< 1,900	< 2,100	< 1,900	< 2,000	< 2,000	ug/Kg
4-Nitrophenol	< 1,900	< 1,900	< 2,100	<1,900	< 2,000	< 2,000	ug/Kg

TABLE 2 (Page 2 of 2) Summary of Semi-Volatile Organic Analyses, Storage Pad SP-2 General Electric Company, Bloomington, Illinois

			Sample 1	Number ¹			
Parameter	SP2-1-1	SP2-2-1	SP2-3-1	SP2-4-1	SP2-5-1	SP2-6-1	Units
Dibenzofuran	< 390	<400	<430	<380	<400	<420	ug/Kg
2,4-Dinitrotoluene	< 390	< 400	< 430	<380	< 400	< 420	ug/Kg
Diethylphthalate	<390	< 400	< 430	<380	< 400	< 420	ug/Kg
4-Chlorophenyl-phenylethe	r <390	<400	<430	< 380	< 400	<420	ug/Kg
Fluorene	<390	< 400	< 430	< 380	< 400	< 420	ug/Kg
4-Nitroaniline	< 1,900	< 1,900	< 2,100	< 1,900	< 2,000	< 2,000	ug/Kg
4,6-Dinitro-2-methylphenol	l < 1,900	< 1,900	< 2,100	< 1,900	< 2,000	< 2,000	ug/Kg
N-Nitrosodiphenylamine	< 390	<400	< 430	<380	< 400	< 420	ug/Kg
4-Bromophenyl-phenylethe	r < 390	<400	< 430	<380	< 400	< 420	ug/Kg
Hexachlorobenzene	< 390	< 400	< 430	<380	< 400	< 420	ug/Kg
Pentachlorophenol	< 1,900	< 1,900	< 2,100	< 1,900	< 2,000	< 2,000	ug/Kg
Phenanthrene	< 390	< 400	<430	< 380	< 400	< 420	ug/Kg
Anthracene	< 390	< 400	< 430	<380	< 400	< 420	ug/Kg
Di-n-butylphthalate	< 390	< 400	< 430	<380	< 400	< 420	ug/Kg
Fluoranthene	< 390	< 400	< 430	<380	< 400	< 420	ug/Kg
Pyrene	< 390	< 400	< 430	<380	< 400	< 420	ug/Kg
Butylbenzylphthalate	< 390	< 400	<430	<380	< 400	< 420	ug/Kg
3,3-Dichlorobenzidine	< 780	<800	<860	< <i>7</i> 70	< 800	< 850	ug/Kg
Benzo(a)anthracene	< 390	< 400	<430	< 380	< 400	< 420	ug/Kg
Chrysene	<390	< 400	< 430	<380	< 400	< 420	ug/Kg
bis(2-Ethylhexyl)phthalate	370 JB	500 B	470 B	370 JB	510 B	1,600 B	ug/Kg
Di-n-Octyl Phthalate	< 390	< 400	< 430	< 380	< 400	< 420	ug/Kg
Benzo(b)fluroanthene	< 390	< 400	< 430	< 380	< 400	< 420	ug/Kg
Benzo(k)fluroanthene	< 390	< 400	< 430	< 380	< 400	< 420	ug/Kg
Benzo(a)pyrene	< 390	< 400	< 430	< 380	< 400	< 420	ug/Kg
Indeno(1,2,3-cd)pyrene	< 390	< 400	< 430	<380	< 400	< 420	ug/Kg
Dibenzo(a,h)anthracene	< 390	< 400	< 430	<380	< 400	< 420	ug/Kg
Benzo(g,h,i)perylene_	< 390	<400	<430	<380	< 400	< 420	ug/Kg
Ethylmethylbenzene 2	•	130-180	-	-	•	-	ug/Kg

NOTES: 1. See Figure 2 for sample locations and Appendix A for laboratory reports. See attached Supplemental Notes.

- 2. Tentatively identified compound (TIC). Concentration estimated.
- 3. Unknown compounds detected in all samples. See Appendix A.

TABLE 3
Summary of TCLP Metals, Reactivity and Corrosivity Analyses, Storage Pad SP-2
General Electric Company, Bloomington, Illinois

							Sample	Number ¹					IEPA Site	
Parameter	SP2-1-1	SP2-1-2	SP2-2-1	SP2-2-2	SP2-3-1	SP2-3-2	SP2-4-1	SP2-4-2	SP2-5-1	SP2-5-2	SP2-6-1	SP2-6-2	Objective	Units
Arsenic	< 0.0045	< 0.0045	< 0.0045	< 0.0045	< 0.0045	< 0.0045	< 0.0045	< 0.0045	< 0.0045	< 0.0045	< 0.0045	< 0.0045	NA	mg/L
Barium	1.4	1.1	1.4	0.76	1.1	1.0	1.2	1.3	1.8	1.1	1.3	0.98	5.0	mg/L
Cadmium	4.8	0.29	4.9	3.8	0.091	0.83	< 0.005	0.014	1.4	1.3	0.32	< 0.005	0.05	mg/L
Chromium	< 0.01	< 0.01	< 0.01	< 0.01	< 0.01	< 0.01	< 0.01	< 0.01	< 0.01	< 0.01	0.10	< 0.01	1.0	mg/L
Lead	< 0.002	< 0.002	< 0.002	< 0.002	< 0.002	< 0.002	< 0.002	< 0.002	0.002	< 0.002	< 0.002	< 0.002	0.1	mg/L
Mercury	< 0.0002	0.00061	< 0.0002	0.00023	< 0.0002	< 0.0002	< 0.0002	0.0013	< 0.0002	< 0.002	< 0.0002	0.0012	2.0	mg/L
Nickel	< 0.04	< 0.04	< 0.04	< 0.04	< 0.04	< 0.04	< 0.04	< 0.04	< 0.04	< 0.04	< 0.04	< 0.04	2.0	mg/L
Sclenium	< 0.0045	< 0.0045	< 0.0045	< 0.0045	< 0.0045	< 0.0045	< 0.0045	< 0.0045	< 0.0045	< 0.0045	< 0.0045	< 0.0045	NA	mg/L
Silver	< 0.01	0.017	< 0.01	0.017	< 0.01	0.018	< 0.01	0.016	< 0.01	0.026	< 0.01	0.032	NA	mg/L
Reactive Cyanide	1.5	< 0.35	1.4	< 0.33	0.24	< 0.31	0.48	< 0.37	< 0.30	< 0.25	< 0.28	< 0.43	NA	mg/kg
Corrosivity	7.6	8.2	8.6	9.0	6.8	7.7	7.6	7.8	7.8	8.6	6.7	6.7	NA	pH Units

NOTES: 1. See Figure 2 for sample locations and Appendix A for laboratory reports. See Supplemental Notes.

TABLE 4 (Page 1 of 2)
Summary of Volatile Organic Analyses, Storage Pad SP-1
General Electric Company, Bloomington, Illinois

				Sample l	Number ¹		IEPA Site	
Parameter	SP1-1-1	SP1-1-2	SP1-2-1*	SP1-2-2	SP1-3-1	SP1-3-2	Objective	Units
						_		
Acetone	15 B	< 12	12 JB	14 B	<11	< 12	700	ug/Kg
Benzene	<6	<6	<6	< 5	<6	<6	NA	ug/Kg
Bromodichloromethane	<6	<6	<6	<5	<6	<6	NA	ug/Kg
Bromoform	<6	<6	<6	<5	<6	<6	NA	ug/Kg
Bromomethane	<11	< 12	<12	< 10	<11	<12	NA	ug/Kg
2-Butanone	< 11	< 12	<12	< 10	<11	< 12	NA	ug/Kg
Carbon Disulfide	<6	<6	<6	<5	<6	<6	NA	ug/Kg
Carbon Tetrachloride	<6	<6	<6	<5	<6	<6	NA	ug/Kg
Chlorobenzene	<6	<6	<6	< 5	<6	<6	NA	ug/Kg
Chloroethane	<11	< 12	< 12	< 10	< 11	< 12	NA	ug/Kg
Chloroform	<6	<6	<6	<5	<6	<6	NA	ug/Kg
Chloromethane	< 11	< 12	<12	< 10	< 11	< 12	NA	ug/Kg
Dibromochloromethane	<6	<6	<6	< 5	<6	<6	NA	ug/Kg
1,1-Dichloroethane	<6	<6	<6	< 5	<6	<6	NA	ug/Kg
1,2-Dichloroethane	<6	<6	<6	<5	<6	<6	NA	ug/Kg
1,1-Dichloroethene	<6	<6	<6	<5	<6	<6	35	ug/Kg
1,2-Dichloroethene (total)	<6	<6	<6	<5	<6	<6	700	ug/Kg
1,2-Dichloropropane	<6	<6	<6	<5	<6	<6	NA	ug/Kg
cis-1,3-Dichloropropene	<6	<6	<6	<5	<6	<6	NA	ug/Kg
trans-1,3-Dichloropropene	<6	<6	<6	<5	<6	<6	NA	ug/Kg
Ethylbenzene	<6	<6	<6	<5	<6	<6	1,000	ug/Kg
2-Hexanone	< 11	< 12	< 12	< 10	< 11	< 12	NA	ug/Kg
Methylene Chloride	<6	<6	<6	<5	<6	<6	25	ug/Kg
4-Methyl-2-Pentanone	< 11	< 12	< 12	< 10	< 11	< 12	NA	ug/Kg
Styrene	<6	<6	<6	<5	<6	<6	NA	ug/Kg
1,1,2,2-Tetrachloroethane	<6	<6	<6	< 5	<6	<6	NA	ug/Kg
Tetrachloroethene	<6	<6	<6	<5	<6	<6	NA	ug/Kg
Toluene	<6	<6	<6	<5	<6	<6	5,000	ug/Kg
1,1,1-Trichloroethane	<6	<6	<6	<5	<6	<6	1,000	ug/Kg
1,1,2-Trichloroethane	<6	<6	<6	<5	<6	·<6	NA	ug/Kg
Trichloroethene	<6	<6	<6	<5	3 J	39	125	ug/Kg
Vinyl Acetate	< 11	< 12	< 12	< 10	<11	< 12	NA	ug/Kg
Vinyl Chloride	<11	< 12	<12	< 10	<11	< 12	10	ug/Kg
Xylene (total)	<6	<6	<6	<5	<6	<6	10,000	ug/Kg
1,1,2-Trichloro-1,2,2-trifluoroethane	² 7	-	-	8	-	11	NA	ug/Kg

TABLE 4 (Page 2 of 2)
Summary of Volatile Organic Analyses, Storage Pad SP-1
General Electric Company, Bloomington, Illinois

Parameter	SP1-4-1	Sample I SP1-4-2	Number ¹ SP1-5-1	SP1-5-2	IEPA Site Objective	Units
Acetone	12	< 12	< 12	< 12	700	ug/Kg
Benzene	<6	<6	<6	<6	NA	ug/Kg
Bromodichloromethane	<6	<6	<6	<6	NA	ug/Kg
Bromoform	<6	<6	<6	<6	NA	ug/Kg
Bromomethane	<11	< 12	< 12	< 12	NA	ug/Kg
2-Butanone	< 11	< 12	< 12	< 12	NA	ug/Kg
Carbon Disulfide	<6	<6	<6	<6	NA	ug/Kg
Carbon Tetrachloride	<6	<6	<6	<6	NA	ug/Kg
Chlorobenzene	<6	<6	<6	<6	NA	ug/Kg
Chloroethane	<11	<12	< 12	< 12	NA	ug/Kg
Chloroform	<6	<6	<6	<6	NA	ug/Kg
Chloromethane	< 11	< 12	< 12	< 12	NA	ug/Kg
Dibromochloromethane	<6	<6	<6	<6	NA	ug/Kg
1,1-Dichloroethane	<6	<6	<6	<6	NA	ug/Kg
1,2-Dichloroethane	<6	<6	<6	<6	NA	ug/Kg
1,1-Dichloroethene	<6	<6	<6	<6	35	ug/Kg
1,2-Dichloroethene (total)	<6	<6	<6	<6	700	ug/Kg
1,2-Dichloropropane	<6	<6	<6	<6	NA	ug/Kg
cis-1,3-Dichloropropene	<6	<6	<6	<6	NA	ug/Kg
trans-1,3-Dichloropropene	<6	<6	<6	<6	NA	ug/Kg
Ethylbenzene	<6	<6	<6	<6	1,000	ug/Kg
2-Hexanone	< 11	< 12	< 12	< 12	NA	ug/Kg
Methylene Chloride	<6	<6	<6	<6	25	ug/Kg
4-Methyl-2-Pentanone	< 11	< 12	<12	< 12	NA	ug/Kg
Styrene	<6	<6	<6	<6	NA	ug/Kg
1,1,2,2-Tetrachloroethane	<6	<6	<6	<6	NA	ug/Kg
Tetrachloroethene	< 6	<6	22	<6	NA	ug/Kg
Toluene	2 J	<6	2 J	<6	5,000	ug/Kg
1,1,1-Trichloroethane	4 J	<6	3 J	<6	1,000	ug/Kg
1,1,2-Trichloroethane	<6	<6	<6	<6	NA	ug/Kg
Trichloroethene	110	25	120	60	25	ug/Kg
Vinyl Acetate	< 11	< 12	<12	<12	NA	ug/Kg
Vinyl Chloride	< 11	<12	<12	< 12	10	ug/Kg
Xylene (total)	<6	<6	<6	<6	10,000	ug/Kg
1,1,2-Trichloro-1,2,2-trifluoroethane ²	9	7	•	7	NA	ug/Kg

NOTES: 1. See Figure 3 for sample locations and Appendix A for laboratory reports. See attached Supplemental Notes.

2. Tentatively identified compound (TIC). Concentration estimated.

TABLE 5 (Page 1 of 2)
Summary of Semi-Volatile Organic Analyses, Storage Pad SP-1
General Electric Company, Bloomington, Illinois

			Sample N	Sample Number ¹					
Parameter	SP1-1-1	SP1-2-1	SP1-3-1	SP1-4-1	SP1-5-1	Units			
m	400	- 200	. 200	1700	- 190	(7/-			
Phenol	<380	<380	<380	<380	< 380	ug/Kg			
bis(2-Chloroethyl)ether	<380	< 380	<380	<380	< 380	ug/Kg			
2-Chlorophenol	<380	<380	< 380	<380	<380	ug/Kg			
1,3-Dichlorobenzene	< 380	< 380	<380	<380	<380	ug/Kg			
1,4-Dichlorobenzene	<380	<380	<380	<380	<380	ug/Kg			
Benzyl alcohol	< 380	<380	<380	<380	<380	ug/Kg			
1,2-Dichlorobenzene	< 380	<380	<380	<380	< 380	ug/Kg			
2-Methylphenol	< 380	< 380	<380	<380	< 380	ug/Kg			
bis(2-chloroisopropyl)ether	< 380	< 380	<380	<380	<380	ug/Kg			
4-Methylphenol	< 380	< 380	< 380	<380	< 380	ug/Kg			
N-Nitroso-Di-n-propylamine	< 380	< 380	< 380	<380	<380	ug/Kg			
Hexachloroethane	< 380	<380	<380	<380	<380	ug/Kg			
Nitrobenzene	< 380	<380	<380	< 380	< 380	ug/Kg			
Isophorone	< 380	<380	<380	<380	<380	ug/Kg			
2-Nitrophenol	< 380	<380	<380	< 380	< 380	ug/Kg			
2,4-Dimethylphenol	< 380	<380	<380	<380	<380	ug/Kg			
Benzoic acid	< 1,800	< 1,900	< 1,800	< 1,800	< 1,900	ug/Kg			
bis(2-Chloroethoxy)methane	< 380	< 380	< 380	<380	<380	ug/Kg			
2,4-Dichlorophenol	< 380	< 380	< 380	< 380	<380	ug/Kg			
1,2,4-Trichlorobenzene	< 380	< 380	< 380	< 380	< 380	ug/Kg			
Naphthalene	< 380	< 380	< 380	<380	< 380	ug/Kg			
4-Chloroaniline	< 380	<380	< 380	< 380	< 380	ug/Kg			
4-Hexachlorobutadiene	< 380	<380	< 380	< 380	<380	ug/Kg			
4-Chloro-3-methylphenol	< 380	< 380	< 380	< 380	< 380	ug/Kg			
2-Methylnaphthalene	< 380	< 380	< 380	< 380	< 380	ug/Kg			
Hexachlorocyclopentadiene	<380	<380	<380	< 380	< 380	ug/Kg			
2,4,6-Trichlorophenol	< 380	< 380	<380	<380	< 380	ug/Kg			
2,4,5-Trichlorophenol	< 1,800	< 1,900	< 1,800	< 1,800	< 1,900	ug/Kg			
2-Chloronaphthalene	< 380	< 380	< 380	< 380	< 380	ug/Kg			
2-Nitroaniline	< 1,800	< 1,900	< 1,800	< 1,800	< 1,900	ug/Kg			
Dimethylphthalate	< 380	< 380	<380	< 380	< 380	ug/Kg			
Acenaphthylene	<380	< 380	<380	<380	<380	ug/Kg			
2,6-Dinitrotoluene	< 380	<380	<380	<380	< 380	ug/Kg			
3-Nitroaniline	< 1,800	< 1,900	<1,800	< 1,800	< 1,900	ug/Kg			
Acenaphthene	<380	<380	<380	<380	<380	ug/Kg			
2,4-Dinitrophenol	< 1,800	< 1,900	< 1,800	< 1,800	< 1,900	ug/Kg			
4-Nitrophenol	< 1,800	< 1,900	< 1,800	< 1,800	< 1,900	ug/Kg			
	- , -	•	•	•	•				

TABLE 5 (Page 2 of 2)
Summary of Semi-Volatile Organic Analyses, Storage Pad SP-1
General Electric Company, Bloomington, Illinois

			Sample N	lumber ¹		
Parameter	SP1-1-1	SP1-2-1	SP1-3-1	SP1-4-1	SP1-5-1	Units
Dibenzofuran	<380	< 380	< 380	< 380	<380	ug/Kg
2,4-Dinitrotoluene	< 380	< 380	< 380	< 380	<380	ug/Kg
Diethylphthalate	< 380	< 380	< 380	< 380	< 380	ug/Kg
4-Chlorophenyl-phenylether	< 380	< 380	< 380	< 380	<380	ug/Kg
Fluorene	< 380	< 380	< 380	<380	<380	ug/Kg
4-Nitroaniline	< 1,800	< 1,900	< 1,800	< 1,800	< 1,900	ug/Kg
4,6-Dinitro-2-methylphenol	< 1,400	< 1,900	< 1,800	< 1,800	< 1,900	ug/Kg
N-Nitrosodiphenylamine	< 380	< 380	< 380	<380	<380	ug/Kg
4-Bromophenyl-phenylether	< 380	< 380	<380	< 380	<380	ug/Kg
Hexachlorobenzene	< 380	< 380	< 380	< 380	<380	ug/Kg
Pentachlorophenol	< 1,400	< 1,900	< 1,800	< 1,800	< 1,900	ug/Kg
Phenanthrene	< 380	< 380	< 380	< 380	< 380	ug/Kg
Anthracene	< 380	< 380	< 380	< 380	< 380	ug/Kg
Di-n-butylphthalate	< 380	< 380	<380	< 380	< 380	ug/Kg
Fluoranthene	250 J	< 380	< 380	< 380	< 380	ug/Kg
Pyrene	230 J	< 380	<380	< 380	<380	ug/Kg
Butylbenzylphthalate	< 380	< 380	< 380	<380	< 380	ug/Kg
3,3-Dichlorobenzidine	< 750	< 770	< 750	< 760	< 770	ug/Kg
Benzo(a)anthracene	< 380	< 380	< 380	<380	<380	ug/Kg
Chrysene	< 380	< 380	<380	< 380	<380	ug/Kg
bis(2-Ethylhexyl)phthalate	260 J	270 JB	430 B	410 B	430 B	ug/Kg
Di-n-Octyl Phthalate	< 380	< 380	< 380	< 380	< 380	ug/Kg
Benzo(b)fluroanthene	< 380	< 380	< 380	< 380	< 380	ug/Kg
Benzo(k)fluroanthene	< 380	< 380	< 380	< 380	< 380	ug/Kg
Benzo(a)pyrene	< 380	< 380	< 380	< 380	< 380	ug/Kg
Indeno(1,2,3-cd)pyrene	<380	< 380	< 380	< 380	< 380	ug/Kg
Dibenzo(a,h)anthracene	< 380	< 380	< 380	< 380	< 380	ug/Kg
Benzo(g,h,i)perylene	<380	< 380	< 380	< 380	<380	ug/Kg
1,13-Tetradecadiene ²	140	-	-	-	-	ug/Kg

NOTES: 1. See Figure 3 for sample locations and Appendix A for laboratory reports. See attached Supplemental Notes.

- 2. Tentatively identified compound (TIC). Concentration estimated.
- 3. Unknown compounds detected in all samples. See Appendix A.

TABLE 6
Summary of TCLP Metals, Reactivity and Corrosivity Analyses, Storage Pad SP-1
General Electric Company, Bloomington, Illinois

					Sample N	lumber ¹					IEPA Site	
Parameter	SP1-1-1	SP1-1-2	SP1-2-1	SP1-2-2	SP1-3-1	SP1-3-2	SP1-4-1	SP1-4-2	SP1-5-1	SP1-5-2	Objective	Units
Arsenic	< 0.0045	< 0.0045	<0.0045	< 0.0045	< 0.0045	< 0.0045	< 0.0045	< 0.0045	< 0.0045	< 0.0045	NA	mg/L
Barium	1.0	0.9	1.1	1.3	0.96	0.7	0.83	0.7	1.0	1.1	5.0	mg/L
Cadmium	< 0.005	0.029	0.006	0.008	0.015	0.006	0.007	< 0.005	0.007	< 0.005	0.05	mg/L
Chromium	< 0.01	< 0.01	< 0.01	< 0.01	< 0.01	< 0.01	< 0.01	< 0.01	< 0.01	< 0.01	1.0	mg/L
Lead	< 0.002	< 0.002	< 0.002	< 0.002	< 0.002	< 0.002	< 0.002	< 0.002	< 0.002	< 0.002	0.1	mg/L
Mercury	< 0.0002	< 0.0002	< 0.0002	0.0034	< 0.0002	< 0.0002	< 0.0002	< 0.0002	< 0.0002	< 0.0002	NA	mg/L
Nickel	< 0.04	< 0.04	< 0.04	< 0.04	< 0.04	< 0.04	< 0.04	< 0.04	< 0.04	< 0.04	2.0	mg/L
Selenium	< 0.0045	< 0.0045	< 0.0045	< 0.0045	< 0.0045	< 0.0045	< 0.0045	< 0.0045	< 0.0045	< 0.0045	NA	mg/L
Silver	< 0.01	0.022	< 0.01	< 0.01	< 0.01	< 0.01	< 0.01	< 0.01	< 0.01	< 0.01	NA	mg/L
Reactive Cyanide	0.51	< 0.33	< 0.30	< 0.32	0.37	< 0.36	0.35	< 0.37	1.3	< 0.32	NA	mg/L
Corrosivity	7.5	8.6	7.4	7.7	7.7	7.8	7.9	7.7	8.0	7.3	NA	pH Units

NOTES: 1. See Figure 3 for sample locations and Appendix A for laboratory reports. See Supplemental Notes.

TABLE 7
Summary of Volatile Organics Analyses, Former Incinerator
General Electric Company, Bloomington, Illinois

Parameter	FI-1-1	FI-1-1R	Sample E FI-1-2	Number 1 FI-2-1	FI-2-2*	FI-2-2RE	Units
a ameter	11-1-1	1 1-1-11	L 11-1-2	1,1-7-1	t 1-7-7	r 1-4-2RE	Units
Acetone	8 JB	13 B	21 B	10 JB	14 B	9 JB	ug/Kg
Benzene	<6	<6	<6	<5	<6	<6	ug/Kg
Bromodichloromethane	<6	<6	<6	<5	<6	<6	ug/Kg
Bromoform	<6	<6	<6	<5	<6	<6	ug/Kg
Bromomethane	< 13	< 13	< 13	< 11	< 11	<11	ug/Kg
2-Butanone	< 13	< 13	<13	<11	<11	<11	ug/Kg
Carbon Disulfide	<6	<6	<6	<5	<6	<6	ug/Kg
Carbon Tetrachloride	<6	<6	<6	< 5	<6	<6	ug/Kg
Chlorobenzene	<6	<6	<6	< 5	<6	<6	ug/Kg
Chloroethane	<13	< 13	<13	<11	<11	<11	ug/Kg
Chloroform	<6	<6	<6	< 5	<6	<6	ug/Kg
Chloromethane	<13	< 13	< 13	< 11	< 11	<11	ug/Kg
Dibromochloromethane	<6	<6	<6	<5	<6	<6	ug/Kg
1,1-Dichloroethene	<6	<6	<6	< 5	<6	<6	ug/Kg
1,2-Dichloroethene (total)	<6	<6	<6	< 5	<6	<6	ug/Kg
1,1-Dichloroethane	<6	<6	<6	< 5	<6	<6	ug/Kg
1,2-Dichloroethane	<6	<6	<6	< 5	<6	<6	ug/Kg
1,2-Dichloropropane	<6	<6	<6	<5	<6	<6	ug/Kg
cis-1,3-Dichloropropane	<6	<6	<6	<5	<6	<6	ug/Kg
trans-1,3-Dichloropropane	<6	<6	<6	<5	<6	<6	ug/Kg
Ethylbenzene	<6	<6	<6	<5	<6	<6	ug/Kg
2-Нехапопе	< 13	<13	<13	<11	< 11	<11	ug/Kg
Methylene Chloride	<6	<6	<6	<5	<6	<6	ug/Kg
4-Methyl-2-Pentanone	< 13	< 13	< 13	< 11	< 11	<11	ug/Kg
Styrene	<6	<6	<6	< 5	<6	<6	ug/Kg
Tetrachloroethene	<6	<6	<6	< 5	<6	<6	ug/Kg
1,1,2,2-Tetrachloroethane	<6	<6	<6	< 5	<6	<6	ug/Kg
Toluene	<6	<6	3 J	3 J	5 J	3 J	ug/Kg
1,1,1-Trichloroethane	<6	<6	<6	< 5	<6	<6	ug/Kg
1,1,2-Trichloroethane	<6	<6	<6	< 5	<6	<6	ug/Kg
Trichloroethene	<6	<6	<6	<5	6	2 J	ug/Kg
Vinyl Acetate	< 13	< 13	<13	< 11	<11	<11	ug/Kg
Vinyl Chloride	<13	<13	<13	<11	<11	<11	ug/Kg
Xylene (total)	2 < 6	<6	<6	<5	<6	<6	ug/Kg
1,1,2-Trichloro-1,2,2-trifluoro	ethane ² -	•	14	•	20	-	ug/Kg

NOTES: 1. See Figure 3 for sample locations and Appendix A for laboratory reports. See attached Supplemental Notes.

^{2.} Tentatively identified compound (TIC). Concentration estimated.

^{3.} Sample FI-1-1 reanalyzed by laboratory (FI-1-1RE). See Appendix A.

TABLE 8
Summary of TCLP Metals, Reactivity and Corrosivity Analyses, Former Incinerator
General Electric Company, Bloomington, Illinois

	Sample Number ¹				
Parameter	FI-1-1	FI-1-2	FI-2-1	FI-2-2	Units
Arsenic	< 0.0045	< 0.0045	< 0.0045	< 0.0045	mg/L
Barium	0.93	1.2	1.3	1.1	mg/L
Cadmium	< 0.005	< 0.005	0.28	0.087	mg/L
Chromium	< 0.01	< 0.01	0.017	< 0.01	mg/L
Lead	< 0.002	0.0056	0.57	0.003	mg/L
Mercury	< 0.0002	0.0008	< 0.0002	0.0039	mg/L
Nickel	< 0.04	< 0.04	0.29	< 0.04	mg/L
Selenium	< 0.0045	< 0.0045	< 0.0045	< 0.0045	mg/L
Silver	< 0.01	< 0.01	< 0.01	0.04	mg/L
Reactive Cyanide	0.40	< 0.33	< 0.33	< 0.30	mg/kg
Corrosivity	6.5	6.0	7.7	7.9	pH Units

NOTES: 1. See Figure 3 for sample locations and Appendix A for laboratory reports. See Supplemental Notes.

FIGURES

11 m




Figure 1

SITE LOCATION MAP

GENERAL ELECTRIC

Bloomington, Illinois

HARZA

ENVIRONMENTAL SERVICES, INC. Consuling Engineers

